

STEKE

SHIP TO:

LA 71282

API OUTDOORS INC
C/O GREG PAVIS
602 KIMBROUGH DR
TALLULAH

71282

CUST NO: 060938 C.O.D

WRITE

☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CYCLE	A1	B1				
TRIGGER GROUP		B2	"... sometimes it goes off by itself..."			
BOLT ASSY.		B3		E1	E2	F1
BARREL ASSY.		B4	D1	E3		F3
REC. ASSY.		B5	D2	E4		F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Rifle cannot be made to malfunction - operates properly in every respect. I disassembly of rifle disclosed trigger assembly is overly oily, dirty & rusty. Entire bottom end of receiver and barrel is filthy!! Firearm exhibits no maintenance at all.
Trigger pull 4 $\frac{3}{4}$ #; an-lift .011"

[illegible]

FD6925 REV. 1/92