

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

Mr. C. M. Armfield  
Route 1, Box 250  
Allendale, SC 29810

March 5, 1987

Dear Mr. Armfield:

This is in reply to your recent letter involving the difficulties you've experienced with your Model 600 rifle, serial # 75093.

As we've never heard of a Remington gun firing spontaneously without manipulation of any mechanism, we are very much interested in examining your rifle.

However, we are currently conducting a trigger replacement program for certain concerned lots of Model 600 series firearms. This program has been nationally advertised over a period of years and involves complete fire assembly replacement for these guns at no charge.

Therefore, we ask that you please package your Model 600 and send it via United Parcel Service, Transportation C.O.D. to:

Remington Arms Co., Inc.  
Product Service Dept.  
Rush Attn: R. H. Potter  
14 Hoefler Ave  
Ilion, NY 13357

Enclosed for more timely service in this busy season are three (3) blaze orange stickers which you should affix to both butt ends and to the top of the outside of the package. Please also include a copy of this letter in with the rifle.

A new fire assembly will then be installed and the rifle will be shipped, prepaid, to your home address. The gun will be returned to you in complete, safe operating condition, and we assure you that you'll experience no further problems.

As Remington has no type of gun trade-in program, we cannot be of assistance to you in that area. However, if you do decide to trade or sell the rifle, you can be absolutely sure that the gun will be in safe condition for the new owner if the trigger is replaced per our instructions.