

---

**From:** Norton, Vince  
**Sent:** Wednesday, October 03, 2007 4:29 PM  
**To:** Diaz, Danny  
**Cc:** McCollum, James M.  
**Subject:** REQUISITION  
**Attachments:** image001.gif

1003010852 – 30 receiver inserts from U of L for the Model 710 fire control.

During assembly of the DAT fire controls there was an issue with the trigger pull adjustment. The fix requires a change to the insert. I will discuss the problem with you when you get back in the office.  
Vince