

December 18, 1978

Remington Arms Company, Inc.  
939 Barnum Avenue  
Bridgeport, Connecticut 06602



Gentlemen:

Recently, I purchased a Remington Model 700 BDL, 25;06 rifle, serial no. A6427943. The gun is in excellent condition and was purchased as a used rifle from a local trader.

The gun has gone off twice now, once shooting a hole in the floorboard of my fathers truck and the second time knocking a chunk out of my front porch. Both times the safety was pushed foward to remove a shell from the chamber when the discharge occured. The trigger was not touched in either incident.

I haved carried the gun to three different gunsmiths and dealers concerning this matter. All three believe the trouble lies in the trigger. Each suggested I write a letter to you stating the problem and return the gun with the letter.

I have hardly shot a full box of shells through the rifle and the gunsmiths state that not much more than that was shot before I bought it. These incidents concern me greatly and I would like to correct the problem as soon as possible. No one has taken the gun apart to actually locate the trouble.

Please notify me of your procedures concerning such matters as this.

Sincerely,

A handwritten signature in cursive script, appearing to read "Kenneth L. Arnold".

Kenneth L. Arnold  
3401 Rustwood  
Lufkin, Texas 75901

ph. no. (713) 875-2865

