

ROYAL BUSINESS GROUP INC. / TORONTO, ONT. M5H 1A5 / (416) 593-2152

RECEIVING AND ESTIMATING REPORT

FROM. DATE _____

ORDER R 15056

DATE RECEIVED _____ ESTIMATED _____

DATE OPENED 7-23-85 VIA UPSMODEL AND GRADE. 600 - 308 winSERIAL NO. 84057stuck not our manufacture / studsDATE CODE XM 12-65

FROM:

Bill Ashbeck
10390 106 Place NORTH
Maple Grove, MN. 55369

REPAIR CHARGE _____

INS. _____

UPS _____

PARCEL POST _____

TOTAL \$ _____

GUN CONDITION: (NEW) (SLIGHTLY WORN) (VERY WORN) (MISUSED) (QUOTE)

CUSTOMER'S COMPLAINT Rifle fired on putting safety on
safe position (engaged)

MAIN FAULT

No malfunction found - trigger
assembly is sound + proper.DEMERIT
CODE

PARTS

- ① Install new fire
assembly under
modification program
no charge
- ② Install new recoil
pad + send gun to
customer's address
COD for pad charge.
RKH 8-21

FOR COMPUTER REFER. ONLY

PROOF _____

(CLEAN) (TEST) (TARGET)