

the Crosby group
INC.

BILL ASHBECK
DISTRICT REPRESENTATIVE

612-424-0883
10380 109th PLACE
MAPLE GROVE, MN 55369

Dear Mr. Potter

7-1-85

Per our conversation. Work of 7-1-85
about my Remington Model #600 Serial
#84057 308 cal.

Russ Likkila of Bigging and Wear
felling, Mr. witness the accident.

Enclosed is a estimate for the window
I had done in 1983. The bullet ripped a little
cloth and lodged into the right window frame.
I will repair the cloth and just put padding
in the door frame.

I purchased the gun in 1968 new
from the Kaiser Club in Germany.

would you please repair the gun
and reimburse me for the new window
the gun shot out.

Please put a new pad on the butt
I will pay for it.

P.S. I would like to just
see again the fall.

Regards
Bill Ashbeck

Functions of this type were experienced
to fire the rifle upon safety engagement and upon safety release,
the only manner in which your rifle was made to fire was to release
the safety and to pull the trigger.

Even though your Model 600 is involved in a trigger modification
program, the trigger mechanism in your particular firearm is in
safe, proper working condition. Only a small percentage of the

BLVD
326 GENEVA AVENUE
OAKDALE, MN 55358-8128
VE W
433 UNIVERSITY AVE
ST. PAUL, MN 55101
LVA
81-8770

ROSEVILLE, CA
3731 SO. ROBERTSON
ST. PAUL, MN 55101

DATE 7-1-85

RESIDENCE PHONE

BUSINESS PHONE

UNIT PRICE

AMOUNT

288.05

230.44

27.90

375

14.06

276.35

near safety can from
firing pin from moving
"on", there is no way
the primer and fire the
it is a mechanical impos-
sibility engaged.

the rifle upon safety
the trigger, and no mal-

After numerous attempts