

RECEIVING AND ESTIMATING REPORT

COMMENTS

R ORDER
94-12942INITIAL
PPS

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ACCESSORIES

W/STUDS

SCOPE MNTS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

AUSTIN, CHARLES
229 E. MT. KIRK AVE.
NORRISTOWN

PA 19403

AUSTIN, CHARLES
229 E. MT. KIRK AVE.
NORRISTOWNPA
19403

CUST NO: 095876 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D2

E4

METAL

C2

D3

E5

F5

MAIN FAULT

Major 4th Unable to duplicate customer concern as rep. Microscopic evaluation reveals that rear engagement with groove has been changed at some time after manufacture. Exchange trigger assy. We do not recommend that trigger assy be adjusted outside of factory. Special price getting of good will and to restore customer confidence in rifle.

PARTS

Trigger Assy Complete
Non bolt lock safety

COMMENTS

Trigger pull measured 3# as rec'd.
sear lift was .0055

Firing pin and spring rusty

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94