

NEW SERIAL NUMBER

MODEL AND GRADE

700 25-06

BOL

It stands to reason when unloading the rifle, the left hand is on the forearm and the right hand is on the belt. Hardly anyway could the trigger be touched.

I don't believe this rifle has been fired since this incident in question as I gave up hunting and the rifle has been in my gun cabinet ever since.

I would appreciate your inspecting this rifle for the possible cause of it missing.

I also had conversation with a Jerry Beaton in your company.

Respectfully Yours
Charles Austin

These people
need an
exchange
of good
rifles.

val 3# or rec
0055

only rusty

GALLERY TESTER

DATE

TEST

TARGET

PATTERN

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94