

MODEL 710 BASIC JACK FUNCTION TEST					
PROJECT# 241095					
TLW 0010AA					
9/13/00					
Tech.- Jesse Arnold & Bob Lee					
GUN	AMMO	ROUNDS	STEM LOW	BOLT OVERRIDE	F.T.E.
B-11	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40	7		
	REM PRT3006B 165GR	40	7		
	REM R30063 150GR	40	1		
B-12	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40	3		
B-13	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40	4		
B-14	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40			
B-15	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40			
B-16	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			

ET07101

	REM PRT3006B 165GR	40				
	REM R30063 150GR	40		1		
B-17	REM R30065 180GR	40				
	REM R30067 220GR	40				
	UMC L30062 150GR	40				
	REM PRT3006B 165GR	40				
	REM R30063 150GR	40				
B-18	REM R30065 180GR	40				
	REM R30067 220GR	40				
	UMC L30062 150GR	40				
	REM PRT3006B 165GR	40				
	REM R30063 150GR	40	1			
B-19	REM R30065 180GR	40				
	REM R30067 220GR	40				
	UMC L30062 150GR	40				
	REM PRT3006B 165GR	40				
	REM R30063 150GR	40				
B-20	REM R30065 180GR	40				
	REM R30067 220GR	40				
	UMC L30062 150GR	40				
	REM PRT3006B 165GR	40				
	REM R30063 150GR	40	1			
	GRAND TOTAL	RDS = 2000	24	2	1	
	MAFUNCTION RATE=	1.35%				
NOTE: BOLT VERY STIFF CLOSING THE BOLT WHEN CHAMBERING A ROUND.						
DURING TESTING THERE WERE MANY PROBLEMS WITH THE MAG BOX HOUSINGS COMING APART AT THE SPOT WELD.						
SOME OF THE MALFUNCTIONS MAY BE ATTRIBUTED THE MAG BOX ISSUE						

83

ET07102

Confidential - Subject - 5.22.060001271
 Williams v. Remington