

---

**From:** Ronkainen, Jim  
**Sent:** Thursday, March 29, 2007 12:40 PM  
**To:** Snedeker, Jim  
**Subject:** FW: Failure Report - 40X XMP Trigger TA#12 Accidental Impact  
**Attachments:** IMP2170a TA#12 Trigger Failure by Accidental Impact.pdf

FYI. For some reason, the link in Marlin's message didn't work for me – not sure why.

**Jim Ronkainen**  
Staff Engineer  
Remington Arms Co. Inc.  
R&D Technical Center  
315 W. Ring Road  
Elizabethtown, KY 42701  
(270) 769-7613 (phone)  
(270) 737-9576 (fax)  
[jim.ronkainen@remington.com](mailto:jim.ronkainen@remington.com)  
visit us at [www.remington.com](http://www.remington.com)

---

**From:** Jiranek, Marlin R.  
**Sent:** Thursday, March 29, 2007 11:09 AM  
**To:** Ronkainen, Jim  
**Cc:** Franz, Scott  
**Subject:** Failure Report - 40X XMP Trigger TA#12 Accidental Impact

The report is located in the completed work folder in LabWIP. Let me know if you have any questions.

<I:\Completed Work\IMP2170a TA#12 Trigger Failure by Accidental Impact.pdf>

Marlin.

**Marlin R. Jiranek, II**  
*Senior Research Engineer*  
Remington Arms Company, Inc.  
315 West Ring Road  
Elizabethtown, KY 42701  
(270) 769-7645 Phone  
(270) 737-9576 FAX  
[marlin.jiranek@remington.com](mailto:marlin.jiranek@remington.com)