

RECEIVING AND ESTIMATING REPORT

BARBER - Kinzer PPS GAL RE0000314

ORDER
R 92-24410

INITIAL JJM	CUSTOMER ORDER NO.		ATTN FRED EMHOF		
DATE RECEIVED 11/12/92	DATE OPENED 11/12/92	DATE CODE DX 9-73	SERIAL NUMBER 6673330	NEW SERIAL NUMBER	MODEL AND GRADE 700 6MM ADL
ACCESSORIES W/STUDS		SCOPE BASE			

FROM:

BAKER, STAN
314 POWELL AVE
P O BOX 338
DUNN

NC 28334

SHIP TO:

BAKER, STAN
314 POWELL AVE
P O BOX 338
DUNN

NC
28334

CUST NO: 070023 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☒ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

- EXCISE
- TAX
- INSURANCE
- UPS
- PARCEL POST
- TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.						
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

AIN FAULT *Could not duplicate complaint. However, it was noted that the trigger assembly had been adjusted outside factory (evident from loose adjustment screws) and, the rear-engagement was insufficient. When the bolt was closed fast, the firing pin would not come out enough, falling down on the cocking spring. Also, there is excessive oil and contamination on the trigger assembly. Trigger pull 5.4 pounds; rear-lift .008"*

RTS	COMMENTS <i>Based on condition of trigger assembly and the fact that the rear-engagement has been engaged with, offer new trigger assembly at no more cost, as a gesture of good will.</i>					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

BARBER - Kinzer PPS GAL RE0000314

PPS 00309