

Centerfire

Summary	Total Tested	11192
	Total Rejected:	361
	Overall Reject Rate:	3.23

Proof	Shot:	5235	830	2009	795	735	765	65							
	Rejected:	34	0	15	5	5	5	0	0	0	0	0	0	0	0
	Percent:	0.6	0.0	0.7	0.6	0.7	0.7	0.0							
Test	Shot:	5378	824	2280	1086	779	700	61							104
	Rejected:	133	15	55	28	56	3	2	0	0	0	0	0	0	2
	Percent:	2.5	1.8	2.4	2.6	7.2	0.4	3.3							1.9
Target	Shot:	441	84	168	79	61	669	6							
	Rejected:	3	0	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.7	0.0	0.0	0.0	0.0	0.0	0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615	Rimfire
AB	Action binds													
BABS	Bulge at body shoulder													
BAC	Burr at chamber													
BBMA	BBL-to-bolt misalignment													
BB	Bolt binds/catches	10		8	2	3	1	1						
BCOAB	Bolt catches on anti-bind													
BCOBS	Bolt catches on bolt stop													
BCOF	Bolt catches on follower			1										
BC	Blows cases													
BHR	Bolt hits receiver													
BHS	Bolt plug hits safety switch													
BLOP	Bar lock or disconnecter out of position													
BLSO	Barrel lug shot off													
BPO	Bolt pulls out			1										
BSSM	Bolt stems shell in magazine													
BWCD	Bolt won't cam down			1		1								
BWCFM	Bolt won't close over full magazine	4			2									
CD	Case dented													
CH	Closes hard	4	1	4		5		1						
CLM	Can't load magazine	2			2	7								
CO	Cut-off													
CR	Cuts rim													
CS	Cases swell													
CTOG	Chamber torn or gouged													
CTP	Creepy trigger pull													
CWSB	Cams wrong side of action bar													
DBB	Doesn't blow back													
DCS	Double click in safety switch													
DCT	Double click in trigger													
DCU	Doesn't close-up													
DE	Doesn't eject	4	4		3									
DEL	Doesn't eject live round													

Centerfire

<i>Grand totals</i>	700 <i>totals</i>	New Gen <i>totals</i>
10434	10434	
64	64	0
0.6	0.6	
11192	11088	
294	292	0
2.6	2.6	
1508	1508	
3	3	0
0.2	0.2	
totals	totals	totals
25	25	
1	1	
1	1	
2	2	
6	6	
15	15	
11	11	
11	11	

## Centerfire

DFB	Doesn't feed back																
DFU	Doesn't feed up																
DLO	Doesn't lock open (after last shell)																
DLU	Doesn't lock-up																1
DS	Dead safe																
DX	Doesn't extract	34	1	13	6	25											
DXL	Doesn't extract live round																
EDS	Extractor drops shell	21	4	4	5	5											
ESB	Ejector sticks back	2	1	2													
ESCR	Empty shell catches receiver																
ESS	Extractor stems shell																
FA	Fires automatically																
FB	Follower binds																
FC	Fails to connect																1
FCB	Fore-end cracked or broken																
FD	Follows-down	1		1													
FF	Fails to fire			1	1												
FFP	Flat firing pin																
FOS	Fires on safe																
FPHB	Firing pin hits bbl																
FPHI	Firing pin hits inside rim																
FPO	Floor plate opens	2				2											
FPOH	Floor plate opens hard																
FSR	Fires when safe is released																
FT	Follower tips																
GCSO	Gas cyl shot off																
HLB	Heavy bolt lift	2															
HMSC	Heading mismatch-steps on case																
HPA	High pressure ammo																
HUR	Hard under rail	6	1														
JCS	Jumps cartridge																
JM	Jumps magazine	1		1													
JO	Jars off																
LB	Light blow																
MAH	Magazine assembles hard																
MCW	Magazine capacity wrong																
MFA	Misfires (ammo)																
MFOP	Magazine follower out of position																
ML	Magazine loose	12															
MLH	Magazine loads hard																
MRH	Magazine removes hard	4															
OH	Opens hard	1			1												
OR	Over-rides	3		3	2	6											
PH	Pulls hard																
PSI	Proof stamp illegible																
PSM	Proof stamp missing																
RBOC	Rings and bulges on case																
RDW	(Action) release doesn't work		1				2										
RIC	Rings in chamber																
RIS	Ring in sholder																
RS	Rim srem																



Centerfire

SBC	Stems bottom chambers	2		1															
SBE	Stems bbl extension																		
SCB	Stock cracked or broken																		
SCX	Shell catches																		
SHI	Short indent																		
SI	Stems incline	2																	
SIC	Stems in chamber		1	1															
SL	shaves lead																		
SLC	Stems left side of chamber																		
SMOC	Stretch marks on case																		
SOR	Stem over-ride	16	1	7	3	1													
SP	Stems port																		
SR	Shoulder rough																		
SRC	Stems right side of chamber																		
SRIC	Specific rings in chamber																		
SSOC	Surface scratches on case																		
STC	Stems top chamber			4															
SWE	Safety switch works too easily																		
SWH	Safety switch works too hard																		
SWW	Safety Switch won't work																		
TD	Tips down																		
TU	Tips up																		
TWP	Trigger won't pull																		
TWR	Trigger won't retract																		
UNCN-T	Uncoded																		
XH	Extracts hard			2	1														
HI	High																		
LO	Low																		
LEFT	Left																		
RIGHT	Right																		
DG	Doesn't Group																		
FSST	Front sight tipped																		
RSTT	Rear sight tipped																		
RSBR	Rear sight base raised																		
FSTR	Front sight raised																		
FSTL	Front sight loose																		
RSTL	Rear sight loose																		
MGPT-G	Missing parts at target																		
UNCN-G	Uncoded nonconformity at target	3																	
AI-P	Assembly incomplete at proof																		
BBB	Barrel bracket cracked or broken at proof																		
BC-P	Blows cases at proof																		
BEB-P	Barrel extension broken at proof																		
BLP-P	Blanked primer at proof																		
BLSO-P	Barrel lug shot off at proof																		
BP-P	Blown primer at proof																		
BS-P	Barrel split at proof																		
DBF-P	Damaged Bolt Face	17		9	3	1	4												
DLOS-P	Doesn't lock over shells at proof																		



Centerfire

ESBBP-P	Ejector sticks back -Blown Primer cup	1												
ESBEC-P	Ejector sticks back - Ejector Cresent	2		1										
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof	2				1								
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions	12		5	2	4								

Centerfire

1	1	
3	3	
3	3	
23	23	



Gallery Top Faults for 700's - Current month through:									
<div><div></div>&lt;autodate</div>									
00100102030405060708091	Action kinds								
	Bulge at body shoulder								
	Burr at chamber								
	BL - no bolt misalignment								
	Bolt thicknesses								
	Bolt catches on bolt stop								
	Bolt catches on follower								
	Blows cases								
	Bolt hits receiver								
	Jacking into safety with								
	Bar lock or disconnector out of position								
	Barrel lug slot off								
	Bolt pulls out								
	Bolt stems wheel in magazine								
	Bolt won't cam down								
	Bolt won't close over full magazine								
	Case deformed								
	Closes hard								
	Car't load magazine								
	Cut-off								

AB	Action binds	0
BABS	Bulge at body shoulder	0
BAC	Burr at chamber	0
BBMA	BBL-to-bolt misalignment	0
BB	Bolt binds/catches	0
BCOBS	Bolt catches on bolt stop	0
BCOF	Bolt catches on follower	0
BC	Blows cases	0
BHR	Bolt hits receiver	0
BHS	Bolt plug hits safety switch	0
BLOP	Bar lock or disconnecter out of position	0
BLSO	Barrel lug shot off	0
BPO	Bolt pulls out	0
BSSM	Bolt stems shell in magazine	0
BWCD	Bolt won't cam down	0
BWCFM	Bolt won't close over full magazine	0
CD	Case dented	0
CH	Closes hard	0
CLM	Can't load magazine	0
CO	Cut-off	0
CR	Cuts rim	0
CS	Cases swell	0
CTOG	Chamber torn or gouged	0
CTP	Creepy trigger pull	0
CWSB	Cams wrong side of action bar	0
DBB	Doesn't blow back	0
DCS	Double click in safety switch	0
DCT	Double click in trigger	0
DCU	Doesn't close-up	0
DE	Doesn't eject	0
DEL	Doesn't eject live round	0
DFB	Doesn't feed back	0
DFU	Doesn't feed up	0
DLO	Doesn't lock open (after last shell)	0
DLU	Doesn't lock-up	0
DS	Dead safe	0
DX	Doesn't extract	0
DXL	Doesn't extract live round	0
EDS	Extractor drops shell	0
ESB	Ejector sticks back	0
ESCR	Empty shell catches receiver	0
ESS	Extractor stems shell	0
FA	Fires automatically	0
FB	Follower binds	0
FC	Fails to connect	0
FCB	Fore-end cracked or broken	0
FD	Follows-down	0
FF	Fails to fire	0
FFP	Flat firing pin	0

FOS	Fires on safe	0
FPHB	Firing pin hits bbl	0
FPHI	Firing pin hits inside rim	0
FPO	Floor plate opens	0
FPOH	Floor plate opens hard	0
FSR	Fires when safe is released	0
FT	Follower tips	0
GCSO	Gas cyl shot off	0
HBL	Heavy bolt lift	0
HMSC	Heading mismatch-steps on case	0
HPA	High pressure ammo	0
HUR	Hard under rail	0
JCS	Jumps cartridge	0
JM	Jumps magazine	0
JO	Jars off	0
LB	Light blow	0
MAH	Magazine assembles hard	0
MCW	Magazine capacity wrong	0
MFA	Misfires (ammo)	0
MFOP	Magazine follower out of position	0
ML	Magazine loose	0
MLH	Magazine loads hard	0
MRH	Magazine removes hard	0
OH	Opens hard	0
OR	Over-rides	0
PH	Pulls hard	0
PSI	Proof stamp illegible	0
PSM	Proof stamp missing	0
RBOC	Rings and bulges on case	0
RDW	(Action) release doesn't work	0
RIC	Rings in chamber	0
RIS	Ring in sholder	0
RS	Rim srem	0
SBC	Stems bottom chambers	0
SBE	Stems bbl extension	0
SCB	Stock cracked or broken	0
SCX	Shell catches	0
SHI	Short indent	0
SI	Stems incline	0
SIC	Stems in chamber	0
SL	shaves lead	0
SLC	Stems left side of chamber	0
SMOC	Stretch marks on case	0
SOR	Stem over-ride	0
SP	Stems port	0
SR	Shoulder rough	0
SRC	Stems right side of chamber	0
SRIC	Specific rings in chamber	0
SSOC	Surface scratches on case	0

STC	Stems top chamber	0
SWE	Safety switch works too easily	0
SWH	Safety switch works too hard	0
SWW	Safety Switch won't work	0
TD	Tips down	0
TU	Tips up	0
TWP	Trigger won't pull	0
TWR	Trigger won't retract	0
UNCN-T	Uncoded	0
XH	Extracts hard	0
		0
HI	High	0
LO	Low	0
LEFT	Left	0
RIGHT	Right	0
DG	Doesn't Group	0
FSST	Front sight tipped	0
RSTT	Rear sight tipped	0
RSBR	Rear sight base raised	0
FSTR	Front sight raised	0
FSTL	Front sight loose	0
RSTL	Rear sight loose	0
MGPT-G	Missing parts at target	0
UNCN-G	Uncoded nonconformity at target	0
		0
AI-P	Assembly incomplete at proof	0
BBB	Barrel bracket cracked or broken at proof	0
BC-P	Blows cases at proof	0
BEB-P	Barrel extension broken at proof	0
BLP-P	Blanked primer at proof	0
BLSO-P	Barrel lug shot off at proof	0
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DBF-P	Damaged Bolt Face	0
DLOS-P	Doesn't lock over shells at proof	0
ESBBP-P	Ejector sticks back -Blown Primer cup	0
ESBEC-P	Ejector sticks back - Ejector Crescent	0
FCB-P	Fore-end cracked at proof	0
FESO-P	Fore-end shot off at proof	0
FF-P	Fails to fire at proof	0
GCSO-P	Gas cylinder shot off at proof	0
MSI-P	Magnaflux stamp illegible on bbl	0
MSM-P	Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	0
SCB-P	Stock cracked or broken at proof	0
BCOAB	Bolt catches on anti-bind	
BCOAB	Bolt catches on anti-bind	

<autodate  
>-1

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												



## Page 16 of 284

[illegible]



[illegible]

## Gallery Performance Report

[illegible]

# Gallery Performance Report

Proof - Test - Target

Page 19 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	597	Test Date:									
	Total Rejected:	12										
	Overall Reject Rate:	2.01										

Proof	Shot:	194	40	98	123	96	50						
	Rejected:	0	0	0	1	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.8	0.0	0.0						
Test	Shot:	187	39	105	104	112	50						
	Rejected:	1	0	5	0	5	0	0	0	0	0	0	0
	Percent:	0.5	0.0	4.8	0.0	4.5	0.0						
Target	Shot:	17	3	11	11	9	50						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches			1									
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower			1									
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard			1									
CLM	Can't load magazine					5							
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

Proof - Test - Target

[illegible]

**SUBJECT TO PROTECTIVE ORDER - KINZER V. REMINGTON**

**BARBER - RE 0006362**



[illegible]

## Page 26 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face				1								
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	651	Test Date:									
	Total Rejected:	14										
	Overall Reject Rate:	2.15										

Proof	Shot:	183	200	89	75	28	77						
	Rejected:	2	0	3	0	0	1	0	0	0	0	0	0
	Percent:	1.1	0.0	3.4	0.0	0.0	1.3						
Test	Shot:	161	211	104	75	33	67						
	Rejected:	2	0	2	3	0	1	0	0	0	0	0	0
	Percent:	1.2	0.0	1.9	4.0	0.0	1.5						
Target	Shot:	14	22	6	2	3	66						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches						1						
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

Proof - Test - Target

<b><i>totals</i></b>	
----------------------	--

652	0	6	0.9
-----	---	---	-----

651	0	8	1.2
-----	---	---	-----

113	0	0.0
-----	---	-----

[illegible]

## Page 32 of 284

[illegible]





## Page 34 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1		2			1						
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent			1									
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof	1											
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												



Gallery Performance Report

Summary	Total Tested	562	Test Date:
	Total Rejected:	37	
	Overall Reject Rate:	6.58	

Proof	Shot:	376		28	29	52	42						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0	0.0						
Test	Shot:	376	11	45	44	71							
	Rejected:	20	2	2	3	9	0	0	0	0	0	0	0
	Percent:	5.3	18.2	4.4	6.8	12.7							
Target	Shot:	20	1	5	5	7							
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	1				2							
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine	3											
CD	Case dented												
CH	Closes hard		1	1									
CLM	Can't load magazine					1							
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

Proof - Test - Target

[illegible]

## Page 40 of 284

[illegible]



		3
	1	1
		3
		1
		1
		1
		6

## Page 42 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: D66  
Comment: ingairy:  
308

Gallery Performance Report

Summary	Total Tested	645	Test Date:
	Total Rejected:	19	
	Overall Reject Rate:	2.95	

Proof	Shot:	370		67	51	47	48	24					
	Rejected:	5	0	0	0	0	0	0	0	0	0	0	0
	Percent:	1.4		0.0	0.0	0.0	0.0	0.0					
Test	Shot:	365		136	51	21	29	24					
	Rejected:	4	0	1	4	2	1	1	0	0	0	0	0
	Percent:	1.1		0.7	7.8	9.5	3.4	4.2					
Target	Shot:	38		16	6	2	28	2					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0	0.0	0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches			1		1		1					
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine					1							
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target

[illegible]



## Page 49 of 284

[illegible]

[illegible]

## Page 51 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions	5												

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: D163  
Comment: ingalry:  
broken triggers

Gallery Performance Report

Summary	Total Tested	679	Test Date:									
	Total Rejected:	14										
	Overall Reject Rate:	2.06										

Proof	Shot:	290	80	217	44							
	Rejected:	2	0	3	0	0	0	0	0	0	0	0
	Percent:	0.7	0.0	1.4	0.0							
Test	Shot:	288	80	232	69		10					
	Rejected:	3	3	1	2	0	0	0	0	0	0	0
	Percent:	1.0	3.8	0.4	2.9		0.0					
Target	Shot:	23	7	17	3		10					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0		0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine				2								
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												



## Proof - Test - Target

[illegible]

## Page 58 of 284

[illegible]

[illegible]

## Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1		3									
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent	1											
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	274	Test Date:
	Total Rejected:	9	
	Overall Reject Rate:	3.28	

Proof	Shot:	23			14	25						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0			0.0	0.0						
Test	Shot:	67	52		36	68	51					
	Rejected:	0	5	0	0	4	0	0	0	0	0	0
	Percent:	0.0	9.6		0.0	5.9	0.0					
Target	Shot:	3				2	25					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0				0.0	0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard					4							
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												



## Proof - Test - Target

[illegible]

## Page 66 of 284

[illegible]

[illegible]

## Page 68 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												



## Gallery Performance Report

**SUBJECT TO PROTECTIVE ORDER - KINZER V. REMINGTON**

**BARBER - RE 0006412**

# Gallery Performance Report

Proof - Test - Target

Page 75 of 284

## Page 76 of 284



Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													



Gallery Performance Report

Summary	Total Tested	683	Test Date:									
	Total Rejected:	7										
	Overall Reject Rate:	1.02										

Proof	Shot:	100		269	21		79					
	Rejected:	1	0	1	0	0	3	0	0	0	0	0
	Percent:	1.0		0.4	0.0		3.8					
Test	Shot:	177		253	148	7	98					
	Rejected:	0	0	1	0	0	1	0	0	0	0	0
	Percent:	0.0		0.4	0.0	0.0	1.0					
Target	Shot:	14		16			55					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0			0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												



## Proof - Test - Target

[illegible]

## Page 82 of 284

[illegible]

[illegible]

## Page 84 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1		1			3						
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	715	Test Date:
	Total Rejected:	28	
	Overall Reject Rate:	3.92	

Proof	Shot:	360	109	31	104								
	Rejected:	0	0	0	3	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	2.9								
Test	Shot:	361	118	92	142	2							
	Rejected:	16	4	1	4	0	0	0	0	0	0	0	0
	Percent:	4.4	3.4	1.1	2.8	0.0							
Target	Shot:	36	15	3	15								
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0								

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	1			1								
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard			1									
CLM	Can't load magazine	1											
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												



## Gallery Performance Report

Proof - Test - Target

[illegible]

## Gallery Performance Report

DE	Doesn't eject			Proof - Test - Target										
DEL	Doesn't eject live round													
DFB	Doesn't feed back													
DFU	Doesn't feed up													
DLO	Doesn't lock open (after last shell)													
DLU	Doesn't lock-up													
DS	Dead safe													
DX	Doesn't extract	6			3									
DXL	Doesn't extract live round													
EDS	Extractor drops shell	6	3											
ESB	Ejector sticks back		1											
ESCR	Empty shell catches receiver													
ESS	Extractor stems shell													
FA	Fires automatically													
FB	Follower binds													
FC	Fails to connect													
FCB	Fore-end cracked or broken													
FD	Follows-down													
FF	Fails to fire													
FFP	Flat firing pin													
FOS	Fires on safe													
FPHB	Firing pin hits bbl													
FPHI	Firing pin hits inside rim													
FPO	Floor plate opens													
FPOH	Floor plate opens hard													
FSR	Fires when safe is released													
FT	Follower tips													
GCSO	Gas cyl shot off													
HL	Heavy bolt lift													
HMSC	Heading mismatch-steps on case													
HPA	High pressure ammo													
HUR	Hard under rail													
JCS	Jumps cartridge													
JM	Jumps magazine													
JO	Jars off													
LB	Light blow													
MAH	Magazine assembles hard													
MCW	Magazine capacity wrong													
MFA	Misfires (ammo)													
MFOP	Magazine follower out of position													
ML	Magazine loose													
MLH	Magazine loads hard													
MRH	Magazine removes hard													
OH	Opens hard	1												
OR	Over-rides													
PH	Pulls hard													
PSI	Proof stamp illegible													
PSM	Proof stamp missing													
RBOC	Rings and bulges on case													

# Gallery Performance Report

[illegible]

## Page 92 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face				2								
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions				1								

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: G163  
Comment: ingalry: safety arm broke off



Gallery Performance Report

Summary	Total Tested	618	Test Date:
	Total Rejected:	10	
	Overall Reject Rate:	1.62	

Proof	Shot:	147	57	280	60		20	2					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0		0.0	0.0					
Test	Shot:	174	57	293	74		20						
	Rejected:	4	0	5	1	0	0	0	0	0	0	0	0
	Percent:	2.3	0.0	1.7	1.4		0.0						
Target	Shot:	18	7	17	8		20						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0		0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

Proof - Test - Target

[illegible]

## Page 99 of 284

[illegible]

[illegible]

## Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

## Gallery Performance Report

Proof - Test - Target

Page 104 of 284

[illegible]



Gallery Performance Report

Summary	Total Tested	591	Test Date:									
	Total Rejected:	14										
	Overall Reject Rate:	2.37										

Proof	Shot:	339		268		58						
	Rejected:	2	0	0	0	0	0	0	0	0	0	0
	Percent:	0.6		0.0		0.0						
Test	Shot:	249		255	29	58						
	Rejected:	3	0	4	5	0	0	0	0	0	0	0
	Percent:	1.2		1.6	17.2	0.0						
Target	Shot:	22		14	2	58						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	3											
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard			1									
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

Proof - Test - Target

[illegible]

## Page 107 of 284

[illegible]



## Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face	1												
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions	1												

[illegible]



Gallery Performance Report

Proof - Test - Target

Cell: D163  
Comment: ingalry:  
broken trigger

Gallery Performance Report

Summary	Total Tested	641	Test Date:
	Total Rejected:	27	
	Overall Reject Rate:	4.21	

Proof	Shot:	422		166	22	3	9	2					
	Rejected:	5	0	5	0	0	0	0	0	0	0	0	0
	Percent:	1.2		3.0	0.0	0.0	0.0	0.0					
Test	Shot:	405		160	44	23	9						
	Rejected:	13	0	4	0	0	0	0	0	0	0	0	0
	Percent:	3.2		2.5	0.0	0.0	0.0						
Target	Shot:	26		9	5	2	9						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	4		3									
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine	1											
CD	Case dented												
CH	Closes hard	1											
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target

[illegible]

## Page 116 of 284

[illegible]

[illegible]

## Page 118 of 284

[illegible]



Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1											
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent	1											
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof	1											
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions	2		5									



[illegible]

Gallery Performance Report  
Proof - Test - Target

Cell: F126  
Comment: ilngalry:

Cell: D163  
Comment: ilngalry:  
broken trigger

Cell: F163  
Comment: ilngalry:  
broken trigger

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target

[illegible]

## Page 125 of 284

DE	Doesn't eject			Proof - Test - Target						
DEL	Doesn't eject live round									
DFB	Doesn't feed back									
DFU	Doesn't feed up									
DLO	Doesn't lock open (after last shell)									
DLU	Doesn't lock-up									
DS	Dead safe									
DX	Doesn't extract									
DXL	Doesn't extract live round									
EDS	Extractor drops shell									
ESB	Ejector sticks back									
ESCR	Empty shell catches receiver									
ESS	Extractor stems shell									
FA	Fires automatically									
FB	Follower binds									
FC	Fails to connect									
FCB	Fore-end cracked or broken									
FD	Follows-down									
FF	Fails to fire									
FFP	Flat firing pin									
FOS	Fires on safe									
FPHB	Firing pin hits bolt									
FPHI	Firing pin hits inside rim									
FPO	Floor plate opens									
FPOH	Floor plate opens hard									
FSR	Fires when safe is released									
FT	Follower tips									
GCSO	Gas cyl shot off									
HBL	Heavy bolt lift									
HMSC	Heading mismatch-steps on case									
HPA	High pressure ammo									
HUR	Hard under rail									
JCS	Jumps cartridge									
JM	Jumps magazine									
JO	Jars off									
LB	Light blow									
MAH	Magazine assembles hard									
MCW	Magazine capacity wrong									
MFA	Misfires (ammo)									
MFOP	Magazine follower out of position									
ML	Magazine loose									
MLH	Magazine loads hard									
MRH	Magazine removes hard									
OH	Opens hard									
OR	Over-rides									
PH	Pulls hard									
PSI	Proof stamp illegible									
PSM	Proof stamp missing									
RBOC	Rings and bulges on case									

## Gallery Performance Report

Proof - Test - Target

Page 126 of 284

[illegible]

## Page 127 of 284

[illegible]

## Gallery Performance Report

Proof - Test - Target

Page 128 of 284

[illegible]



Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

## Gallery Performance Report

Proof - Test - Target

Page 130 of 284

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target

[illegible]

**SUBJECT TO PROTECTIVE ORDER - KINZER V. REMINGTON**

**BARBER - RE 0006471**

# Gallery Performance Report

Proof - Test - Target

Page 134 of 284

[illegible]

## Gallery Performance Report

[illegible]

# Gallery Performance Report

Proof - Test - Target

Page 136 of 284

[illegible]



Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

## Gallery Performance Report

Proof - Test - Target

Page 138 of 284

[illegible]

Gallery Performance Report

Summary	Total Tested	685	Test Date:									
	Total Rejected:	16										
	Overall Reject Rate:	2.34										

Proof	Shot:	324	162	37	14	20	78						
	Rejected:	9	0	0	0	0	0	0	0	0	0	0	0
	Percent:	2.8	0.0	0.0	0.0	0.0	0.0						
Test	Shot:	325	189	37	14	20	78						
	Rejected:	6	1	0	0	0	0	0	0	0	0	0	0
	Percent:	1.8	0.5	0.0	0.0	0.0	0.0						
Target	Shot:	28	21	4		2	78						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0		0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	1											
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard	1											
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

Proof - Test - Target

[illegible]

635	9	1.4
-----	---	-----

22	685
----	-----

	133
0	0
	0.0

[illegible]

## Page 141 of 284

[illegible]

[illegible]

## Page 143 of 284

RDW	(Action) release doesn't work
RIC	Rings in chamber
RIS	Ring in sholder
RS	Rim srem
SBC	Stems bottom chambers
SBE	Stems bbl extension
SCB	Stock cracked or broken
SCX	Shell catches
SHI	Short indent
SI	Stems incline
SIC	Stems in chamber
SL	shaves lead
SLC	Stems left side of chamber
SMOC	Stretch marks on case
SOR	Stem over-ride
SP	Stems port
SR	Shoulder rough
SRC	Stems right side of chamber
SRIC	Specific rings in chamber
SSOC	Surface scratches on case
STC	Stems top chamber
SWE	Safety switch works too easily
SVWH	Safety switch works too hard
SWW	Safety Switch won't work
TD	Tips down
TU	Tips up
TWP	Trigger won't pull
TWR	Trigger won't retract
UNCN-T	Uncoded
XH	Extracts hard
HI	High
LO	Low
LEFT	Left
RIGHT	Right
DG	Doesn't Group
FSST	Front sight tipped
RSTT	Rear sight tipped
RSTR	Rear sight base raised
FSTR	Front sight raised
FSTL	Front sight loose
RSTL	Rear sight loose
MGP-G	Missing parts at target:
UNCN-G	Uncoded nonconformity at target
AI-P	Assembly incomplete at proof
BBB	Barrel bracket cracked or broken at proof
BC-P	Blows cases at proof
BEB-P	Barrel extension broken at proof

# Gallery Performance Report

Proof - Test - Target

Page 144 of 284

[illegible]



Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	5											
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions	4											

4	
5	

Gallery Performance Report

Proof - Test - Target

Cell: D163  
Comment: ingalry:  
broken trigger

Gallery Performance Report

Summary	Total Tested	561	Test Date:									
	Total Rejected:	20										
	Overall Reject Rate:	3.57										

Proof	Shot:	352		110	10	4	53						
	Rejected:	1	0	3	0	0	0	0	0	0	0	0	0
	Percent:	0.3		2.7	0.0	0.0	0.0						
Test	Shot:	388		104	16		53						
	Rejected:	4	0	9	0	0	0	0	0	0	0	0	0
	Percent:	1.0		8.7	0.0		0.0						
Target	Shot:	24		11	2		53						
	Rejected:	3	0	0	0	0	0	0	0	0	0	0	0
	Percent:	12.5		0.0	0.0		0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches			1									
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out			1									
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard	1											
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target

	totals
0	529
0.8	4
2.3	661
3.3	13
90	3
0	3
3.3	3.3

## Page 150 of 284

[illegible]

[illegible]

## Gallery Performance Report

[illegible]



[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1		3									
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: D141  
Comment: ingalry:  
broken trigger

Gallery Performance Report

Summary	Total Tested	440	Test Date:
	Total Rejected:	10	
	Overall Reject Rate:	2.27	

Proof	Shot:	253				87	36							
	Rejected:	0	0	0	0	3	0	0	0	0	0	0	0	0
	Percent:	0.0				3.4	0.0							
Test	Shot:	285		25		84	28							
	Rejected:	5	0	0	0	2	0	0	0	0	0	0	0	0
	Percent:	1.8		0.0		2.4	0.0							
Target	Shot:	5		3		9	28							
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0		0.0	0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down					1							
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target

[illegible]

## Page 159 of 284

[illegible]

[illegible]



## Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions					3							



Gallery Performance Report

Proof - Test - Target

Cell: H163  
Comment: ingalry:  
broken trigger

Gallery Performance Report

Summary	Total Tested	520	Test Date:									
	Total Rejected:	33										
	Overall Reject Rate:	6.35										

Proof	Shot:	342		97	20	4	91						
	Rejected:	0	0	0	1	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	5.0	0.0	0.0						
Test	Shot:	323		111			74						
	Rejected:	21	0	9	2	0	0	0	0	0	0	0	0
	Percent:	6.5		8.1			0.0						
Target	Shot:	29		5			74						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0			0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down			1									
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine	1											
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target

## Page 168 of 284

[illegible]



[illegible]

## Page 170 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions					1							

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: G163  
Comment: ingalry:  
broken safe arm

Gallery Performance Report

Summary	Total Tested	669	Test Date:
	Total Rejected:	25	
	Overall Reject Rate:	3.74	

Proof	Shot:	350		105	11	206							
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0							
Test	Shot:	359		103	11	196							
	Rejected:	4	0	1	0	20	0	0	0	0	0	0	0
	Percent:	1.1		1.0	0.0	10.2							
Target	Shot:	39		8		9							
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0		0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches			1									
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard	1				1							
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target

[illegible]



## Page 177 of 284



## Page 179 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													



Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target



## Page 185 of 284



## Page 187 of 284



Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													



Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target



**BARBER - RE 0006531**

Page 193 of 284



## Page 195 of 284



Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													



Gallery Performance Report

Summary	Total Tested	434	Test Date:
	Total Rejected:	12	
	Overall Reject Rate:	2.76	

Proof	Shot:	238	92		30	77	52						
	Rejected:	0	0	0	0	1	0	0	0	0	0	0	0
	Percent:	0.0	0.0		0.0	1.3	0.0						
Test	Shot:	297			45	92							
	Rejected:	0	0	0	0	11	0	0	0	0	0	0	0
	Percent:	0.0			0.0	12.0							
Target	Shot:	28			3	9							
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0			0.0	0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target



## Page 201 of 284



## Page 203 of 284

# Gallery Performance Report

Proof - Test - Target

Page 204 of 284

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions					1							



Gallery Performance Report

Proof - Test - Target

Cell: H163  
Comment: ingalry:  
broken trigger

Gallery Performance Report

Summary	Total Tested	686	Test Date:
	Total Rejected:	33	
	Overall Reject Rate:	4.81	

Proof	Shot:	405	18	18	97	73	28						
	Rejected:	4	0	0	0	1	1	0	0	0	0	0	0
	Percent:	1.0	0.0	0.0	0.0	1.4	3.6						
Test	Shot:	404	18	79	85	26	56						
	Rejected:	22	0	1	2	2	0	0	0	0	0	0	0
	Percent:	5.4	0.0	1.3	2.4	7.7	0.0						
Target	Shot:	38	2	8	9	3	96						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches				1								
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												



## Proof - Test - Target

## Gallery Performance Report

DE	Doesn't eject			Proof - Test - Target										
DEL	Doesn't eject live round													
DFB	Doesn't feed back													
DFU	Doesn't feed up													
DLO	Doesn't lock open (after last shell)													
DLU	Doesn't lock-up													
DS	Dead safe													
DX	Doesn't extract	3			1									
DXL	Doesn't extract live round													
EDS	Extractor drops shell	1			1									
ESB	Ejector sticks back													
ESCR	Empty shell catches receiver													
ESS	Extractor stems shell													
FA	Fires automatically													
FB	Follower binds													
FC	Fails to connect													
FCB	Fore-end cracked or broken													
FD	Follows-down													
FF	Fails to fire													
FFP	Flat firing pin													
FOS	Fires on safe													
FPHB	Firing pin hits bbl													
FPHI	Firing pin hits inside rim													
FPO	Floor plate opens													
FPOH	Floor plate opens hard													
FSR	Fires when safe is released													
FT	Follower tips													
GCSO	Gas cyl shot off													
HL	Heavy bolt lift	1												
HMSC	Heading mismatch-steps on case													
HPA	High pressure ammo													
HUR	Hard under rail	1												
JCS	Jumps cartridge													
JM	Jumps magazine													
JO	Jars off													
LB	Light blow													
MAH	Magazine assembles hard													
MCW	Magazine capacity wrong													
MFA	Misfires (ammo)													
MFOP	Magazine follower out of position													
ML	Magazine loose	12												
MLH	Magazine loads hard													
MRH	Magazine removes hard	4												
OH	Opens hard													
OR	Over-rides													
PH	Pulls hard													
PSI	Proof stamp illegible													
PSM	Proof stamp missing													
RBOC	Rings and bulges on case													



## Gallery Performance Report



Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	4				1							
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof					1							
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												



Gallery Performance Report

Proof - Test - Target

Cell: D89  
Comment: ingairy:  
11- 338 lapua- box fell out



Gallery Performance Report

Summary	Total Tested	541	Test Date:						
	Total Rejected:	21							
	Overall Reject Rate:	3.88							

Proof	Shot:	190	49	129	84	24	19	37		
	Rejected:	3	0	0	0	0	0	0	0	0
	Percent:	1.6	0.0	0.0	0.0	0.0	0.0	0.0		
Test	Shot:	187	49	146	79	24	19	37		
	Rejected:	5	0	9	2	1	0	1	0	0
	Percent:	2.7	0.0	6.2	2.5	4.2	0.0	2.7		
Target	Shot:	19	6	15	8	4	19	4		
	Rejected:	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0	0.0	0.0		

CODE	MALFUNCTION INDEX	700 SPS	700 SPS	SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750
AB	Action binds										
BABS	Bulge at body shoulder										
BAC	Burr at chamber										
BBMA	BBL-to-bolt misalignment										
BB	Bolt binds/catches				1						
BCOAB	Bolt catches on anti-bind										
BCOBS	Bolt catches on bolt stop										
BCOF	Bolt catches on follower										
BC	Blows cases										
BHR	Bolt hits receiver										
BHS	Bolt plug hits safety switch										
BLOP	Bar lock or disconnecter out of position										
BLSO	Barrel lug shot off										
BPO	Bolt pulls out										
BSSM	Bolt stems shell in magazine										
BWCD	Bolt won't cam down										
BWCFM	Bolt won't close over full magazine										
CD	Case dented										
CH	Closes hard								1		
CLM	Can't load magazine					2					
CO	Cut-off										
CR	Cuts rim										
CS	Cases swell										
CTOG	Chamber torn or gouged										
CTP	Creepy trigger pull										
CWSB	Cams wrong side of action bar										
DBB	Doesn't blow back										
DCS	Double click in safety switch										
DCT	Double click in trigger										
DCU	Doesn't close-up										
DE	Doesn't eject	1									

Gallery Performance Report  
Proof - Test - Target

totals				
				532
0	0	0	0	3
				0.6
				541
0	0	0	0	18
				3.3
				75
0	0	0	0	0
				0.0
7400	7600	7615	Rimfire	totals
				1
				1
				2
				1

### Gallery Performance Report

		Proof - Test - Target							
DEL	Doesn't eject live round								
DFB	Doesn't feed back								
DFU	Doesn't feed up								
DLO	Doesn't lock open (after last shell)								
DLU	Doesn't lock-up								
DS	Dead safe								
DX	Doesn't extract	3		4					
DXL	Doesn't extract live round								
EDS	Extractor drops shell	1		1		1			
ESB	Ejector sticks back			1					
ESCR	Empty shell catches receiver								
ESS	Extractor stems shell								
FA	Fires automatically								
FB	Follower binds								
FC	Fails to connect								
FCB	Fore-end cracked or broken								
FD	Follows-down								
FF	Fails to fire								
FFP	Flat firing pin								
FOS	Fires on safe								
FPHB	Firing pin hits bbl								
FPHI	Firing pin hits inside rim								
FPO	Floor plate opens								
FPOH	Floor plate opens hard								
FSR	Fires when safe is released								
FT	Follower tips								
GCSO	Gas cyl shot off								
HBL	Heavy bolt lift								
HMSC	Heading mismatch-steps on case								
HPA	High pressure ammo								
HUR	Hard under rail								
JCS	Jumps cartridge								
JM	Jumps magazine			1					
JO	Jars off								
LB	Light blow								
MAH	Magazine assembles hard								
MCW	Magazine capacity wrong								
MFA	Misfires (ammo)								
MFOP	Magazine follower out of position								
ML	Magazine loose								
MLH	Magazine loads hard								
MRH	Magazine removes hard								
OH	Opens hard								
OR	Over-rides			1					
PH	Pulls hard								
PSI	Proof stamp illegible								
PSM	Proof stamp missing								
RBOC	Rings and bulges on case								
RDW	(Action) release doesn't work								

[illegible]

## Page 221 of 284

[illegible]

[illegible]

Gallery Performance Report

BLSO-P	Barrel lug shot off at proof			Proof - Test - Target						
BP-P	Blown primer at proof									
BS-P	Barrel split at proof									
DBF-P	Damaged Bolt Face	2								
DLOS-P	Doesn't lock over shells at proof									
ESBBP-P	Ejector sticks back - Blown Primer cup	1								
ESBEC-P	Ejector sticks back - Ejector Cresent									
FCB-P	Fore-end cracked at proof									
FESO-P	Fore-end shot off at proof									
FF-P	Fails to fire at proof									
GCSO-P	Gas cylinder shot off at proof									
MSI-P	Magnaflux stamp illegible on bbl									
MSM-P	Magnaflux stamp missing on bbl									
PP-P	Pierced primer at proof									
SCB-P	Stock cracked or broken at proof									
UNCM-P	Uncoded proof malfunctions									

[illegible]



Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Proof - Test - Target

[illegible]

## Page 227 of 284

[illegible]

[illegible]

## Page 229 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

# Gallery Performance Report

Proof - Test - Target

Page 232 of 284

[illegible]



Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

Proof - Test - Target

Page 234 of 284

[illegible]

## Page 235 of 284

[illegible]

## Gallery Performance Report

Proof - Test - Target

Page 236 of 284

[illegible]

## Page 237 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

## Gallery Performance Report

Proof - Test - Target

[illegible]



Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

## Page 243 of 284

[illegible]

# Gallery Performance Report

Proof - Test - Target

Page 244 of 284

[illegible]

## Page 245 of 284

[illegible]

# Gallery Performance Report

Proof - Test - Target

Page 246 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]



Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												



## Page 251 of 284

[illegible]

# Gallery Performance Report

Proof - Test - Target

Page 252 of 284

[illegible]

## Page 253 of 284

[illegible]

# Gallery Performance Report

Proof - Test - Target

Page 254 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]



Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

Proof - Test - Target

Page 258 of 284

<b>total/s</b>
----------------

	0
	0

	0	0
--	---	---

	0
	0

[illegible]

## Page 259 of 284

[illegible]

[illegible]

## Page 261 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]



Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

## Gallery Performance Report

**BARBER - RE 0006605**Page 267 of 284



## Gallery Performance Report



Gallery Performance Report


BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												


# Gallery Performance Report


Proof - Test - Target

Page 272 of 284









AB	Action binds	0
BABS	Bulge at body shoulder	0
BAC	Burr at chamber	0
BBMA	BBL-to-bolt misalignment	0
BB	Bolt binds/catches	0
BCOAB	Bolt catches on anti-bind	0
BCOBS	Bolt catches on bolt stop	0
BCOF	Bolt catches on follower	0
BC	Blows cases	0
BHR	Bolt hits receiver	0
BHS	Bolt plug hits safety switch	0
BLOP	Bar lock or disconnecter out of position	0
BLSO	Barrel lug shot off	0
BPO	Bolt pulls out	0
BSSM	Bolt stems shell in magazine	0
BWCD	Bolt won't cam down	0
BWCFM	Bolt won't close over full magazine	0
CD	Case dented	0
CH	Closes hard	0
CLM	Can't load magazine	0
CO	Cut-off	0
CR	Cuts rim	0
CS	Cases swell	0
CTOG	Chamber torn or gouged	0
CTP	Creepy trigger pull	0
CWSB	Cams wrong side of action bar	0
DBB	Doesn't blow back	0
DCS	Double click in safety switch	0
DCT	Double click in trigger	0
DCU	Doesn't close-up	0
DE	Doesn't eject	0
DEL	Doesn't eject live round	0
DFB	Doesn't feed back	0
DFU	Doesn't feed up	0
DLO	Doesn't lock open (after last shell)	0
DLU	Doesn't lock-up	0
DS	Dead safe	0
DX	Doesn't extract	0
DXL	Doesn't extract live round	0
EDS	Extractor drops shell	0
ESB	Ejector sticks back	0
ESCR	Empty shell catches receiver	0
ESS	Extractor stems shell	0
FA	Fires automatically	0
FB	Follower binds	0
FC	Fails to connect	0
FCB	Fore-end cracked or broken	0
FD	Follows-down	0
FF	Fails to fire	0

FFP	Flat firing pin	0
FOS	Fires on safe	0
FPHB	Firing pin hits bbl	0
FPHI	Firing pin hits inside rim	0
FPO	Floor plate opens	0
FPOH	Floor plate opens hard	0
FSR	Fires when safe is released	0
FT	Follower tips	0
GCSO	Gas cyl shot off	0
HBL	Heavy bolt lift	0
HMSC	Heading mismatch-steps on case	0
HPA	High pressure ammo	0
HUR	Hard under rail	0
JCS	Jumps cartridge	0
JM	Jumps magazine	0
JO	Jers off	0
LB	Light blow	0
MAH	Magazine assembles hard	0
MCW	Magazine capacity wrong	0
MFA	Misfires (ammo)	0
MFOP	Magazine follower out of position	0
ML	Magazine loose	0
MLH	Magazine loads hard	0
MRH	Magazine removes hard	0
OH	Opens hard	0
OR	Over-rides	0
PH	Pulls hard	0
PSI	Proof stamp illegible	0
PSM	Proof stamp missing	0
RBOC	Rings and bulges on case	0
RDW	(Action) release doesn't work	0
RIC	Rings in chamber	0
RIS	Ring in sholder	0
RS	Rim srem	0
SBC	Stems bottom chambers	0
SBE	Stems bbl extension	0
SCB	Stock cracked or broken	0
SCX	Shell catches	0
SHI	Short indent	0
SI	Stems incline	0
SIC	Stems in chamber	0
SL	shaves lead	0
SLC	Stems left side of chamber	0
SLOC	Stretch marks on case	0
SOR	Stem over-ride	0
SP	Stems port	0
SR	Shoulder rough	0
SRC	Stems right side of chamber	0
SRIC	Specific rings in chamber	0

SSOC	Surface scratches on case	0
STC	Stems top chamber	0
SWE	Safety switch works too easily	0
SWH	Safety switch works too hard	0
SWW	Safety Switch won't work	0
TD	Tips down	0
TU	Tips up	0
TWP	Trigger won't pull	0
TWR	Trigger won't retract	0
UNCN-T	Uncoded	0
XH	Extracts hard	0
		0
HI	High	0
LO	Low	0
LEFT	Left	0
RIGHT	Right	0
DG	Doesn't Group	0
FSST	Front sight tipped	0
RSTT	Rear sight tipped	0
RSBR	Rear sight base raised	0
FSTR	Front sight raised	0
FSTL	Front sight loose	0
RSTL	Rear sight loose	0
MGPT-G	Missing parts at target	0
UNCN-G	Uncoded nonconformity at target	0
		0
AI-P	Assembly incomplete at proof	0
BBB	Barrel bracket cracked or broken at proof	0
BC-P	Blows cases at proof	0
BEB-P	Barrel extension broken at proof	0
BLP-P	Blanked primer at proof	0
BLSO-P	Barrel lug shot off at proof	0
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DBF-P	Damaged Bolt Face	0
DLOS-P	Doesn't lock over shells at proof	0
ESBBP-P	Ejector sticks back -Blown Primer cup	0
ESBEC-P	Ejector sticks back - Ejector Crescent	0
FCB-P	Fore-end cracked at proof	0
FESO-P	Fore-end shot off at proof	0
FF-P	Fails to fire at proof	0
GCSO-P	Gas cylinder shot off at proof	0
MSI-P	Magnaflux stamp illegible on bbl	0
MSM-P	Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	0
SCB-P	Stock cracked or broken at proof	0

AB	Action binds	0
BABS	Bulge at body shoulder	0
BAC	Burr at chamber	0
BBMA	BBL-to-bolt misalignment	0
BB	Bolt binds/catches	0
BCOAB	Bolt catches on anti-bind	0
BCOBS	Bolt catches on bolt stop	0
BCOF	Bolt catches on follower	0
BC	Blows cases	0
BHR	Bolt hits receiver	0
BHS	Bolt plug hits safety switch	0
BLOP	Bar lock or disconnecter out of position	0
BLSO	Barrel lug shot off	0
BPO	Bolt pulls out	0
BSSM	Bolt stems shell in magazine	0
BWCD	Bolt won't cam down	0
BWCFM	Bolt won't close over full magazine	0
CD	Case dented	0
CH	Closes hard	0
CLM	Can't load magazine	0
CO	Cut-off	0
CR	Cuts rim	0
CS	Cases swell	0
CTOG	Chamber torn or gouged	0
CTP	Creepy trigger pull	0
CWSB	Cams wrong side of action bar	0
DBB	Doesn't blow back	0
DCS	Double click in safety switch	0
DCT	Double click in trigger	0
DCU	Doesn't close-up	0
DE	Doesn't eject	0
DEL	Doesn't eject live round	0
DFB	Doesn't feed back	0
DFU	Doesn't feed up	0
DLO	Doesn't lock open (after last shell)	0
DLU	Doesn't lock-up	0
DS	Dead safe	0
DX	Doesn't extract	0
DXL	Doesn't extract live round	0
EDS	Extractor crops shell	0
ESB	Ejector sticks back	0
ESCR	Empty shell catches receiver	0
ESS	Extractor stems shell	0
FA	Fires automatically	0
FB	Follower binds	0
FC	Fails to connect	0
FCB	Fore-end cracked or broken	0
FD	Follows-down	0
FF	Fails to fire	0

FFP	Flat firing pin	0
FOS	Fires on safe	0
FPHB	Firing pin hits bbl	0
FPHI	Firing pin hits inside rim	0
FPO	Floor plate opens	0
FPOH	Floor plate opens hard	0
FSR	Fires when safe is released	0
FT	Follower tips	0
GCSO	Gas cyl shot off	0
HBL	Heavy bolt lift	0
HMSC	Heading mismatch-steps on case	0
HPA	High pressure ammo	0
HUR	Hard under rail	0
JCS	Jumps cartridge	0
JM	Jumps magazine	0
JO	Jers off	0
LB	Light blow	0
MAH	Magazine assembles hard	0
MCW	Magazine capacity wrong	0
MFA	Misfires (ammo)	0
MFOP	Magazine follower out of position	0
ML	Magazine loose	0
MLH	Magazine loads hard	0
MRH	Magazine removes hard	0
OH	Opens hard	0
OR	Over-rides	0
PH	Pulls hard	0
PSI	Proof stamp illegible	0
PSM	Proof stamp missing	0
RBOC	Rings and bulges on case	0
RDW	(Action) release doesn't work	0
RIC	Rings in chamber	0
RIS	Ring in sholder	0
RS	Rim srem	0
SBC	Stems bottom chambers	0
SBE	Stems bbl extension	0
SCB	Stock cracked or broken	0
SCX	Shell catches	0
SHI	Short indent	0
SI	Stems incline	0
SIC	Stems in chamber	0
SL	shaves lead	0
SLC	Stems left side of chamber	0
SLOC	Stretch marks on case	0
SOR	Stem over-ride	0
SP	Stems port	0
SR	Shoulder rough	0
SRC	Stems right side of chamber	0
SRIC	Specific rings in chamber	0



SSOC	Surface scratches on case	0
STC	Stems top chamber	0
SWE	Safety switch works too easily	0
SWH	Safety switch works too hard	0
SWW	Safety Switch won't work	0
TD	Tips down	0
TU	Tips up	0
TWP	Trigger won't pull	0
TWR	Trigger won't retract	0
UNCN-T	Uncoded	0
XH	Extracts hard	0
		0
HI	High	0
LO	Low	0
LEFT	Left	0
RIGHT	Right	0
DG	Doesn't Group	0
FSST	Front sight tipped	0
RSTT	Rear sight tipped	0
RSBR	Rear sight base raised	0
FSTR	Front sight raised	0
FSTL	Front sight loose	0
RSTL	Rear sight loose	0
MGPT-G	Missing parts at target	0
UNCN-G	Uncoded nonconformity at target	0
		0
AI-P	Assembly incomplete at proof	0
BBB	Barrel bracket cracked or broken at proof	0
BC-P	Blows cases at proof	0
BEB-P	Barrel extension broken at proof	0
BLP-P	Blanked primer at proof	0
BLSO-P	Barrel lug shot off at proof	0
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DBF-P	Damaged Bolt Face	0
DLOS-P	Doesn't lock over shells at proof	0
ESBBP-P	Ejector sticks back -Blown Primer cup	0
ESBEC-P	Ejector sticks back - Ejector Crescent	0
FCB-P	Fore-end cracked at proof	0
FESO-P	Fore-end shot off at proof	0
FF-P	Fails to fire at proof	0
GCSO-P	Gas cylinder shot off at proof	0
MSI-P	Magnaflux stamp illegible on bbl	0
MSM-P	Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	0
SCB-P	Stock cracked or broken at proof	0

AB	Action binds	0
BABS	Bulge at body shoulder	0
BAC	Burr at chamber	0
BBMA	BBL-to-bolt misalignment	0
BB	Bolt binds/catches	0
BCOAB	Bolt catches on anti-bind	0
BCOBS	Bolt catches on bolt stop	0
BCOF	Bolt catches on follower	0
BC	Blows cases	0
BHR	Bolt hits receiver	0
BHS	Bolt plug hits safety switch	0
BLOP	Bar lock or disconnecter out of position	0
BLSO	Barrel lug shot off	0
BPO	Bolt pulls out	0
BSSM	Bolt stems shell in magazine	0
BWCD	Bolt won't cam down	0
BWCFM	Bolt won't close over full magazine	0
CD	Case dented	0
CH	Closes hard	0
CLM	Can't load magazine	0
CO	Cut-off	0
CR	Cuts rim	0
CS	Cases swell	0
CTOG	Chamber torn or gouged	0
CTP	Creepy trigger pull	0
CWSB	Cams wrong side of action bar	0
DBB	Doesn't blow back	0
DCS	Double click in safety switch	0
DCT	Double click in trigger	0
DCU	Doesn't close-up	0
DE	Doesn't eject	0
DEL	Doesn't eject live round	0
DFB	Doesn't feed back	0
DFU	Doesn't feed up	0
DLO	Doesn't lock open (after last shell)	0
DLU	Doesn't lock-up	0
DS	Dead safe	0
DX	Doesn't extract	0
DXL	Doesn't extract live round	0
EDS	Extractor drops shell	0
ESB	Ejector sticks back	0
ESCR	Empty shell catches receiver	0
ESS	Extractor stems shell	0
FA	Fires automatically	0
FB	Follower binds	0
FC	Fails to connect	0
FCB	Fore-end cracked or broken	0
FD	Follows-down	0
FF	Fails to fire	0

FFP	Flat firing pin	0
FOS	Fires on safe	0
FPHB	Firing pin hits bbl	0
FPHI	Firing pin hits inside rim	0
FPO	Floor plate opens	0
FPOH	Floor plate opens hard	0
FSR	Fires when safe is released	0
FT	Follower tips	0
GCSO	Gas cyl shot off	0
HBL	Heavy bolt lift	0
HMSC	Heading mismatch-steps on case	0
HPA	High pressure ammo	0
HUR	Hard under rail	0
JCS	Jumps cartridge	0
JM	Jumps magazine	0
JO	Jers off	0
LB	Light blow	0
MAH	Magazine assembles hard	0
MCW	Magazine capacity wrong	0
MFA	Misfires (ammo)	0
MFOP	Magazine follower out of position	0
ML	Magazine loose	0
MLH	Magazine loads hard	0
MRH	Magazine removes hard	0
OH	Opens hard	0
OR	Over-rides	0
PH	Pulls hard	0
PSI	Proof stamp illegible	0
PSM	Proof stamp missing	0
RBOC	Rings and bulges on case	0
RDW	(Action) release doesn't work	0
RIC	Rings in chamber	0
RIS	Ring in sholder	0
RS	Rim srem	0
SBC	Stems bottom chambers	0
SBE	Stems bbl extension	0
SCB	Stock cracked or broken	0
SCX	Shell catches	0
SHI	Short indent	0
SI	Stems incline	0
SIC	Stems in chamber	0
SL	shaves lead	0
SLC	Stems left side of chamber	0
SMOC	Stretch marks on case	0
SOR	Stem over-ride	0
SP	Stems port	0
SR	Shoulder rough	0
SRC	Stems right side of chamber	0
SRIC	Specific rings in chamber	0

SSOC	Surface scratches on case	0
STC	Stems top chamber	0
SWE	Safety switch works too easily	0
SWH	Safety switch works too hard	0
SWW	Safety Switch won't work	0
TD	Tips down	0
TU	Tips up	0
TWP	Trigger won't pull	0
TWR	Trigger won't retract	0
UNCN-T	Uncoded	0
XH	Extracts hard	0
		0
HI	High	0
LO	Low	0
LEFT	Left	0
RIGHT	Right	0
DG	Doesn't Group	0
FSST	Front sight tipped	0
RSTT	Rear sight tipped	0
RSBR	Rear sight base raised	0
FSTR	Front sight raised	0
FSTL	Front sight loose	0
RSTL	Rear sight loose	0
MGPT-G	Missing parts at target	0
UNCN-G	Uncoded nonconformity at target	0
		0
AI-P	Assembly incomplete at proof	0
BBB	Barrel bracket cracked or broken at proof	0
BC-P	Blows cases at proof	0
BEB-P	Barrel extension broken at proof	0
BLP-P	Blanked primer at proof	0
BLSO-P	Barrel lug shot off at proof	0
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DBF-P	Damaged Bolt Face	0
DLOS-P	Doesn't lock over shells at proof	0
ESBBP-P	Ejector sticks back -Blown Primer cup	0
ESBEC-P	Ejector sticks back - Ejector Crescent	0
FCB-P	Fore-end cracked at proof	0
FESO-P	Fore-end shot off at proof	0
FF-P	Fails to fire at proof	0
GCSO-P	Gas cylinder shot off at proof	0
MSI-P	Magnaflux stamp illegible on bbl	0
MSM-P	Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	0
SCB-P	Stock cracked or broken at proof	0