

Centerfire

Summary	Total Tested	12266
	Total Rejected:	408
	Overall Reject Rate:	3.33

Proof	Shot:	5665	893	2327	853	826	793	158							
	Rejected:	35	0	15	5	5	5	0	0	0	0	0	0	0	0
	Percent:	0.6	0.0	0.6	0.6	0.6	0.6	0.0							
Test	Shot:	5827	887	2572	1124	870	728	154							104
	Rejected:	162	20	55	29	63	4	5	0	0	0	0	0	0	2
	Percent:	2.8	2.3	2.1	2.6	7.2	0.5	3.2							1.9
Target	Shot:	483	89	173	81	70	696	16							
	Rejected:	3	0	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.6	0.0	0.0	0.0	0.0	0.0	0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615	Rimfire
AB	Action binds													
BABS	Bulge at body shoulder													
BAC	Burr at chamber													
BBMA	BBL-to-bolt misalignment													
BB	Bolt binds/catches	14		8	2	3	2	1						
BCOAB	Bolt catches on anti-bind													
BCOBS	Bolt catches on bolt stop													
BCOF	Bolt catches on follower			1										
BC	Blows cases													
BHR	Bolt hits receiver													
BHS	Bolt plug hits safety switch													
BLOP	Bar lock or disconnecter out of position													
BLSO	Barrel lug shot off													
BPO	Bolt pulls out			1										
BSSM	Bolt stems shell in magazine													
BWCD	Bolt won't cam down			1		1								
BWCFM	Bolt won't close over full magazine	4			2									
CD	Case dented													
CH	Closes hard	4	1	4		5		1						
CLM	Can't load magazine	10			2	8								
CO	Cut-off													
CR	Cuts rim													
CS	Cases swell													
CTOG	Chamber torn or gouged													
CTP	Creepy trigger pull													
CWSB	Cams wrong side of action bar													
DBB	Doesn't blow back													
DCS	Double click in safety switch													
DCT	Double click in trigger													
DCU	Doesn't close-up													
DE	Doesn't eject	4	4		3	2								
DEL	Doesn't eject live round													

Centerfire

<i>Grand totals</i>	<i>700 totals</i>	<i>New Gen totals</i>
11515	11515	
65	65	0
0.6	0.6	
12266	12162	
340	338	0
2.8	2.8	
1608	1608	
3	3	0
0.2	0.2	
<i>totals</i>	<i>totals</i>	<i>totals</i>
30	30	
1	1	
1	1	
2	2	
6	6	
15	15	
20	20	
13	13	

Centerfire

DFB	Doesn't feed back														
DFU	Doesn't feed up														
DLO	Doesn't lock open (after last shell)														
DLU	Doesn't lock-up														1
DS	Dead safe					1									
DX	Doesn't extract	35	6	13	6	27		1							
DXL	Doesn't extract live round														
EDS	Extractor drops shell	21	4	4	5	6									
ESB	Ejector sticks back	2	1	2											
ESCR	Empty shell catches receiver														
ESS	Extractor stems shell														
FA	Fires automatically														
FB	Follower binds														
FC	Fails to connect														1
FCB	Fore-end cracked or broken														
FD	Follows-down	1		1											
FF	Fails to fire			1	1										
FFP	Flat firing pin														
FOS	Fires on safe														
FPHB	Firing pin hits bbl														
FPHI	Firing pin hits inside rim														
FPO	Floor plate opens	2				2									
FPOH	Floor plate opens hard														
FSR	Fires when safe is released														
FT	Follower tips														
GCSO	Gas cyl shot off														
HLB	Heavy bolt lift	4													
HMSC	Heading mismatch-steps on case														
HPA	High pressure ammo														
HUR	Hard under rail	6	1			1									
JCS	Jumps cartridge														
JM	Jumps magazine	1		1											
JO	Jars off														
LB	Light blow														
MAH	Magazine assembles hard														
MCW	Magazine capacity wrong														
MFA	Misfires (ammo)														
MFOP	Magazine follower out of position														
ML	Magazine loose	14													
MLH	Magazine loads hard														
MRH	Magazine removes hard	5													
OH	Opens hard	1			1			1							
OR	Over-rides	3		3	2	6									
PH	Pulls hard														
PSI	Proof stamp illegible														
PSM	Proof stamp missing														
RBOC	Rings and bulges on case														
RDW	(Action) release doesn't work		1					2							
RIC	Rings in chamber														
RIS	Ring in sholder														
RS	Rim srem														

Centerfire

SBC	Stems bottom chambers	2		1										
SBE	Stems bbl extension													
SCB	Stock cracked or broken													
SCX	Shell catches													
SHI	Short indent													
SI	Stems incline	2												
SIC	Stems in chamber		1	1				1						
SL	shaves lead													
SLC	Stems left side of chamber													
SMOC	Stretch marks on case													
SOR	Stem over-ride	24	1	7	4	1								
SP	Stems port													
SR	Shoulder rough													
SRC	Stems right side of chamber													
SRIC	Specific rings in chamber													
SSOC	Surface scratches on case													
STC	Stems top chamber	3		4										
SWE	Safety switch works too easily													
SWH	Safety switch works too hard													
SWW	Safety Switch won't work													
TD	Tips down													
TU	Tips up													
TWP	Trigger won't pull													
TWR	Trigger won't retract													
UNCN-T	Uncoded													
XH	Extracts hard			2	1									
HI	High													
LO	Low													
LEFT	Left													
RIGHT	Right													
DG	Doesn't Group													
FSST	Front sight tipped													
RSTT	Rear sight tipped													
RSBR	Rear sight base raised													
FSTR	Front sight raised													
FSTL	Front sight loose													
RSTL	Rear sight loose													
MGPT-G	Missing parts at target													
UNCN-G	Uncoded nonconformity at target	3												
AI-P	Assembly incomplete at proof													
BBB	Barrel bracket cracked or broken at proof													
BC-P	Blows cases at proof													
BEB-P	Barrel extension broken at proof													
BLP-P	Blanked primer at proof													
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face	18		9	3	1	4							
DLOS-P	Doesn't lock over shells at proof													

Centerfire

ESBBP-P	Ejector sticks back -Blown Primer cup	1												
ESBEC-P	Ejector sticks back - Ejector Cresent	2		1										
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof	2				1								
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions	12		5	2	4								

Centerfire

1	1	
3	3	
3	3	
23	23	

Gallery Top Faults for 700's - Current month through:	
<div><autoda...</div>	
1	Action kinds
09	Bulge at body
08	Burr at chamber
07	B.L. or bolt misalignment
06	Bolt thickness
05	Bolt catches on bolt stop
04	Bolt catches on follower
03	Blows cases
02	Both hits receiver
01	Both hits safety
0	Bar lock or disconnector out of position
	Barrel lug shot off
	Bolt pulls out
	Right stems wheel in magazine
	Bolt won't cam down
	Bolt won't cock over full magazine
	Case deformed
	Closes hard
	Car's load
	Cut-off

AB	Action binds	0
BABS	Bulge at body shoulder	0
BAC	Burr at chamber	0
BBMA	BBL-to-bolt misalignment	0
BB	Bolt binds/catches	0
BCOBS	Bolt catches on bolt stop	0
BCOF	Bolt catches on follower	0
BC	Blows cases	0
BHR	Bolt hits receiver	0
BHS	Bolt plug hits safety switch	0
BLOP	Bar lock or disconnecter out of position	0
BLSO	Barrel lug shot off	0
BPO	Bolt pulls out	0
BSSM	Bolt stems shell in magazine	0
BWCD	Bolt won't cam down	0
BWCFM	Bolt won't close over full magazine	0
CD	Case dented	0
CH	Closes hard	0
CLM	Can't load magazine	0
CO	Cut-off	0
CR	Cuts rim	0
CS	Cases swell	0
CTOG	Chamber torn or gouged	0
CTP	Creepy trigger pull	0
CWSB	Cams wrong side of action bar	0
DBB	Doesn't blow back	0
DCS	Double click in safety switch	0
DCT	Double click in trigger	0
DCU	Doesn't close-up	0
DE	Doesn't eject	0
DEL	Doesn't eject live round	0
DFB	Doesn't feed back	0
DFU	Doesn't feed up	0
DLO	Doesn't lock open (after last shell)	0
DLU	Doesn't lock-up	0
DS	Dead safe	0
DX	Doesn't extract	0
DXL	Doesn't extract live round	0
EDS	Extractor drops shell	0
ESB	Ejector sticks back	0
ESCR	Empty shell catches receiver	0
ESS	Extractor stems shell	0
FA	Fires automatically	0
FB	Follower binds	0
FC	Fails to connect	0
FCB	Fore-end cracked or broken	0
FD	Follows-down	0
FF	Fails to fire	0
FFP	Flat firing pin	0

FOS	Fires on safe	0
FPHB	Firing pin hits bbl	0
FPHI	Firing pin hits inside rim	0
FPO	Floor plate opens	0
FPOH	Floor plate opens hard	0
FSR	Fires when safe is released	0
FT	Follower tips	0
GCSO	Gas cyl shot off	0
HBL	Heavy bolt lift	0
HMSC	Heading mismatch-steps on case	0
HPA	High pressure ammo	0
HUR	Hard under rail	0
JCS	Jumps cartridge	0
JM	Jumps magazine	0
JO	Jars off	0
LB	Light blow	0
MAH	Magazine assembles hard	0
MCVW	Magazine capacity wrong	0
MFA	Misfires (ammo)	0
MFOP	Magazine follower out of position	0
ML	Magazine loose	0
MLH	Magazine loads hard	0
MRH	Magazine removes hard	0
OH	Opens hard	0
OR	Over-rides	0
PH	Pulls hard	0
PSI	Proof stamp illegible	0
PSM	Proof stamp missing	0
RBOC	Rings and bulges on case	0
RDW	(Action) release doesn't work	0
RIC	Rings in chamber	0
RIS	Ring in sholder	0
RS	Rim srem	0
SBC	Stems bottom chambers	0
SBE	Stems bbl extension	0
SCB	Stock cracked or broken	0
SCX	Shell catches	0
SHI	Short indent	0
SI	Stems incline	0
SIC	Stems in chamber	0
SL	shaves lead	0
SLC	Stems left side of chamber	0
SMOC	Stretch marks on case	0
SOR	Stem over-ride	0
SP	Stems port	0
SR	Shoulder rough	0
SRC	Stems right side of chamber	0
SRIC	Specific rings in chamber	0
SSOC	Surface scratches on case	0

STC	Stems top chamber	0
SWE	Safety switch works too easily	0
SWH	Safety switch works too hard	0
SWW	Safety Switch won't work	0
TD	Tips down	0
TU	Tips up	0
TWP	Trigger won't pull	0
TWR	Trigger won't retract	0
UNCN-T	Uncoded	0
XH	Extracts hard	0
		0
HI	High	0
LO	Low	0
LEFT	Left	0
RIGHT	Right	0
DG	Doesn't Group	0
FSST	Front sight tipped	0
RSTT	Rear sight tipped	0
RSBR	Rear sight base raised	0
FSTR	Front sight raised	0
FSTL	Front sight loose	0
RSTL	Rear sight loose	0
MGPT-G	Missing parts at target	0
UNCN-G	Uncoded nonconformity at target	0
		0
AI-P	Assembly incomplete at proof	0
BBB	Barrel bracket cracked or broken at proof	0
BC-P	Blows cases at proof	0
BEB-P	Barrel extension broken at proof	0
BLP-P	Blanked primer at proof	0
BLSO-P	Barrel lug shot off at proof	0
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DBF-P	Damaged Bolt Face	0
DLOS-P	Doesn't lock over shells at proof	0
ESBBP-P	Ejector sticks back -Blown Primer cup	0
ESBEC-P	Ejector sticks back - Ejector Crescent	0
FCB-P	Fore-end cracked at proof	0
FESO-P	Fore-end shot off at proof	0
FF-P	Fails to fire at proof	0
GCSO-P	Gas cylinder shot off at proof	0
MSI-P	Magnaflux stamp illegible on bbl	0
MSM-P	Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	0
SCB-P	Stock cracked or broken at proof	0
BCOAB	Bolt catches on anti-bind	
BCOAB	Bolt catches on anti-bind	

<autodate
>-1

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

[illegible]

Page 16 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

Gallery Performance Report

Proof - Test - Target

Page 19 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]

Gallery Performance Report

Summary	Total Tested	597	Test Date:									
	Total Rejected:	12										
	Overall Reject Rate:	2.01										

Proof	Shot:	194	40	98	123	96	50						
	Rejected:	0	0	0	1	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.8	0.0	0.0						
Test	Shot:	187	39	105	104	112	50						
	Rejected:	1	0	5	0	5	0	0	0	0	0	0	0
	Percent:	0.5	0.0	4.8	0.0	4.5	0.0						
Target	Shot:	17	3	11	11	9	50						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches			1									
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower			1									
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard			1									
CLM	Can't load magazine					5							
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Gallery Performance Report

DE	Doesn't eject			Proof - Test - Target										
DEL	Doesn't eject live round													
DFB	Doesn't feed back													
DFU	Doesn't feed up													
DLO	Doesn't lock open (after last shell)													
DLU	Doesn't lock-up													
DS	Dead safe													
DX	Doesn't extract	1		1										
DXL	Doesn't extract live round													
EDS	Extractor drops shell													
ESB	Ejector sticks back													
ESCR	Empty shell catches receiver													
ESS	Extractor stems shell													
FA	Fires automatically													
FB	Follower binds													
FC	Fails to connect													
FCB	Fore-end cracked or broken													
FD	Follows-down													
FF	Fails to fire													
FFP	Flat firing pin													
FOS	Fires on safe													
FPHB	Firing pin hits bbl													
FPHI	Firing pin hits inside rim													
FPO	Floor plate opens													
FPOH	Floor plate opens hard													
FSR	Fires when safe is released													
FT	Follower tips													
GCSO	Gas cyl shot off													
HL	Heavy bolt lift													
HMSC	Heading mismatch-steps on case													
HPA	High pressure ammo													
HUR	Hard under rail													
JCS	Jumps cartridge													
JM	Jumps magazine													
JO	Jars off													
LB	Light blow													
MAH	Magazine assembles hard													
MCW	Magazine capacity wrong													
MFA	Misfires (ammo)													
MFOP	Magazine follower out of position													
ML	Magazine loose													
MLH	Magazine loads hard													
MRH	Magazine removes hard													
OH	Opens hard													
OR	Over-rides													
PH	Pulls hard													
PSI	Proof stamp illegible													
PSM	Proof stamp missing													
RBOC	Rings and bulges on case													

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face				1								
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary		Total Tested	651						Test Date:				
		Total Rejected:	14										
		Overall Reject Rate:	2.15										
Proof	Shot:	183	200	89	75	28	77						
	Rejected:	2	0	3	0	0	1	0	0	0	0	0	0
	Percent:	1.1	0.0	3.4	0.0	0.0	1.3						
Test	Shot:	161	211	104	75	33	67						
	Rejected:	2	0	2	3	0	1	0	0	0	0	0	0
	Percent:	1.2	0.0	1.9	4.0	0.0	1.5						
Target	Shot:	14	22	6	2	3	66						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0	0.0						
CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches						1						
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 32 of 284

[illegible]

[illegible]

Page 34 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1		2			1						
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent			1									
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof	1											
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	562	Test Date:									
	Total Rejected:	37										
	Overall Reject Rate:	6.58										

Proof	Shot:	376		28	29	52	42						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0	0.0						
Test	Shot:	376	11	45	44	71							
	Rejected:	20	2	2	3	9	0	0	0	0	0	0	0
	Percent:	5.3	18.2	4.4	6.8	12.7							
Target	Shot:	20	1	5	5	7							
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	1				2							
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine	3											
CD	Case dented												
CH	Closes hard		1	1									
CLM	Can't load magazine					1							
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 40 of 284

[illegible]

		3
	1	1
		3
		1
		1
		1
		6

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: D66
Comment: ingairy:
308

Gallery Performance Report

Summary	Total Tested	645	Test Date:
	Total Rejected:	19	
	Overall Reject Rate:	2.95	

Proof	Shot:	370		67	51	47	48	24					
	Rejected:	5	0	0	0	0	0	0	0	0	0	0	0
	Percent:	1.4		0.0	0.0	0.0	0.0	0.0					
Test	Shot:	365		136	51	21	29	24					
	Rejected:	4	0	1	4	2	1	1	0	0	0	0	0
	Percent:	1.1		0.7	7.8	9.5	3.4	4.2					
Target	Shot:	38		16	6	2	28	2					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0	0.0	0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches			1		1		1					
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine					1							
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 49 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions	5												

Gallery Performance Report

Proof - Test - Target

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: D163
Comment: ingalry:
broken triggers

Gallery Performance Report

Summary	Total Tested	679	Test Date:									
	Total Rejected:	14										
	Overall Reject Rate:	2.06										

Proof	Shot:	290	80	217	44							
	Rejected:	2	0	3	0	0	0	0	0	0	0	0
	Percent:	0.7	0.0	1.4	0.0							
Test	Shot:	288	80	232	69		10					
	Rejected:	3	3	1	2	0	0	0	0	0	0	0
	Percent:	1.0	3.8	0.4	2.9		0.0					
Target	Shot:	23	7	17	3		10					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0		0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine				2								
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 58 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1		3									
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent	1											
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	274	Test Date:
	Total Rejected:	9	
	Overall Reject Rate:	3.28	

Proof	Shot:	23			14	25						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0			0.0	0.0						
Test	Shot:	67	52		36	68	51					
	Rejected:	0	5	0	0	4	0	0	0	0	0	0
	Percent:	0.0	9.6		0.0	5.9	0.0					
Target	Shot:	3				2	25					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0				0.0	0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard					4							
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 66 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 74 of 284

[illegible]

Gallery Performance Report

Proof - Test - Target

Page 75 of 284

[illegible]

Page 76 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]

Gallery Performance Report

Summary	Total Tested	683	Test Date:									
	Total Rejected:	7										
	Overall Reject Rate:	1.02										

Proof	Shot:	100		269	21		79					
	Rejected:	1	0	1	0	0	3	0	0	0	0	0
	Percent:	1.0		0.4	0.0		3.8					
Test	Shot:	177		253	148	7	98					
	Rejected:	0	0	1	0	0	1	0	0	0	0	0
	Percent:	0.0		0.4	0.0	0.0	1.0					
Target	Shot:	14		16			55					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0			0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 82 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1		1			3						
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	715	Test Date:									
	Total Rejected:	28										
	Overall Reject Rate:	3.92										

Proof	Shot:	360	109	31	104							
	Rejected:	0	0	0	3	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	2.9							
Test	Shot:	361	118	92	142	2						
	Rejected:	16	4	1	4	0	0	0	0	0	0	0
	Percent:	4.4	3.4	1.1	2.8	0.0						
Target	Shot:	36	15	3	15							
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	1			1								
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard			1									
CLM	Can't load magazine	1											
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

SUBJECT TO PROTECTIVE ORDER - KINZER V. REMINGTON

BARBER - RE 0007528

[illegible]

BARBER - RE 0007530

Page 92 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face				2								
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions				1								

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: G163
Comment: ingaly: safety arm broke off

Gallery Performance Report

Summary	Total Tested	618	Test Date:
	Total Rejected:	10	
	Overall Reject Rate:	1.62	

Proof	Shot:	147	57	280	60		20	2					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0		0.0	0.0					
Test	Shot:	174	57	293	74		20						
	Rejected:	4	0	5	1	0	0	0	0	0	0	0	0
	Percent:	2.3	0.0	1.7	1.4		0.0						
Target	Shot:	18	7	17	8		20						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0		0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

SUBJECT TO PROTECTIVE ORDER - KINZER V. REMINGTON

BARBER - RE 0007537

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]

Gallery Performance Report

Summary	Total Tested	591	Test Date:									
	Total Rejected:	14										
	Overall Reject Rate:	2.37										

Proof	Shot:	339		268		58						
	Rejected:	2	0	0	0	0	0	0	0	0	0	0
	Percent:	0.6		0.0		0.0						
Test	Shot:	249		255	29	58						
	Rejected:	3	0	4	5	0	0	0	0	0	0	0
	Percent:	1.2		1.6	17.2	0.0						
Target	Shot:	22		14	2	58						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	3											
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard			1									
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 107 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1											
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions	1											

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: D163
Comment: ingalry:
broken trigger

Gallery Performance Report

Summary	Total Tested	641	Test Date:
	Total Rejected:	27	
	Overall Reject Rate:	4.21	

Proof	Shot:	422		166	22	3	9	2					
	Rejected:	5	0	5	0	0	0	0	0	0	0	0	0
	Percent:	1.2		3.0	0.0	0.0	0.0	0.0					
Test	Shot:	405		160	44	23	9						
	Rejected:	13	0	4	0	0	0	0	0	0	0	0	0
	Percent:	3.2		2.5	0.0	0.0	0.0						
Target	Shot:	26		9	5	2	9						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	4		3									
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine	1											
CD	Case dented												
CH	Closes hard	1											
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 116 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1											
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent	1											
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof	1											
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions	2		5									

[illegible]

Gallery Performance Report
Proof - Test - Target

Cell: F126
Comment: ilngalry:

Cell: D163
Comment: ilngalry:
broken trigger

Cell: F163
Comment: ilngalry:
broken trigger

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

BARBER - RE 0007563

Page 125 of 284

[illegible]

Page 127 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

Gallery Performance Report

Proof - Test - Target

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

[illegible]

Page 133 of 284

[illegible]

Gallery Performance Report

Proof - Test - Target

Page 134 of 284

[illegible]

Page 135 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

Gallery Performance Report

Proof - Test - Target

Page 138 of 284

[illegible]

Gallery Performance Report

Summary	Total Tested	685	Test Date:									
	Total Rejected:	16										
	Overall Reject Rate:	2.34										

Proof	Shot:	324	162	37	14	20	78						
	Rejected:	9	0	0	0	0	0	0	0	0	0	0	0
	Percent:	2.8	0.0	0.0	0.0	0.0	0.0						
Test	Shot:	325	189	37	14	20	78						
	Rejected:	6	1	0	0	0	0	0	0	0	0	0	0
	Percent:	1.8	0.5	0.0	0.0	0.0	0.0						
Target	Shot:	28	21	4		2	78						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0		0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	1											
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard	1											
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Gallery Performance Report

Proof - Test - Target

	totals

635	9	1.4
	0	

22	685
0	7
0.0	1.0

133	0	0.0
-----	---	-----

[illegible]

Page 141 of 284

[illegible]

[illegible]

Page 143 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	5											
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions	4											

4	
5	

Gallery Performance Report

Proof - Test - Target

Cell: D163
Comment: ingalry:
broken trigger

Gallery Performance Report

Summary	Total Tested	561	Test Date:									
	Total Rejected:	20										
	Overall Reject Rate:	3.57										

Proof	Shot:	352		110	10	4	53						
	Rejected:	1	0	3	0	0	0	0	0	0	0	0	0
	Percent:	0.3		2.7	0.0	0.0	0.0						
Test	Shot:	388		104	16		53						
	Rejected:	4	0	9	0	0	0	0	0	0	0	0	0
	Percent:	1.0		8.7	0.0		0.0						
Target	Shot:	24		11	2		53						
	Rejected:	3	0	0	0	0	0	0	0	0	0	0	0
	Percent:	12.5		0.0	0.0		0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches			1									
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out			1									
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard	1											
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 150 of 284

[illegible]

Gallery Performance Report

Proof - Test - Target

Page 151 of 284

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	1		3									
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: D141
Comment: ingalry:
broken trigger

Gallery Performance Report

Summary	Total Tested	440	Test Date:
	Total Rejected:	10	
	Overall Reject Rate:	2.27	

Proof	Shot:	253				87	36							
	Rejected:	0	0	0	0	3	0	0	0	0	0	0	0	0
	Percent:	0.0				3.4	0.0							
Test	Shot:	285		25		84	28							
	Rejected:	5	0	0	0	2	0	0	0	0	0	0	0	0
	Percent:	1.8		0.0		2.4	0.0							
Target	Shot:	5		3		9	28							
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0		0.0	0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down					1							
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 159 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions					3							

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: H163
Comment: ingalry:
broken trigger

Gallery Performance Report

Summary	Total Tested	520	Test Date:									
	Total Rejected:	33										
	Overall Reject Rate:	6.35										

Proof	Shot:	342		97	20	4	91						
	Rejected:	0	0	0	1	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	5.0	0.0	0.0						
Test	Shot:	323		111			74						
	Rejected:	21	0	9	2	0	0	0	0	0	0	0	0
	Percent:	6.5		8.1			0.0						
Target	Shot:	29		5			74						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0			0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down			1									
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine	1											
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 168 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions					1							

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: G163
Comment: ingalry:
broken safe arm

Gallery Performance Report

Summary	Total Tested	669	Test Date:									
	Total Rejected:	25										
	Overall Reject Rate:	3.74										

Proof	Shot:	350		105	11	206						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0	0.0	0.0						
Test	Shot:	359		103	11	196						
	Rejected:	4	0	1	0	20	0	0	0	0	0	0
	Percent:	1.1		1.0	0.0	10.2						
Target	Shot:	39		8		9						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0		0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches			1									
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard	1				1							
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 177 of 284

[illegible]

[illegible]

Page 179 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

[illegible]

Page 185 of 284

[illegible]

[illegible]

Page 187 of 284

[illegible]

Gallery Performance Report

Proof - Test - Target

Page 188 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

[illegible]

Page 193 of 284

[illegible]

[illegible]

Page 195 of 284

[illegible]

Gallery Performance Report

Proof - Test - Target

Page 196 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	434	Test Date:
	Total Rejected:	12	
	Overall Reject Rate:	2.76	

Proof	Shot:	238	92		30	77	52						
	Rejected:	0	0	0	0	1	0	0	0	0	0	0	0
	Percent:	0.0	0.0		0.0	1.3	0.0						
Test	Shot:	297			45	92							
	Rejected:	0	0	0	0	11	0	0	0	0	0	0	0
	Percent:	0.0			0.0	12.0							
Target	Shot:	28			3	9							
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0			0.0	0.0							

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Gallery Performance Report

Proof - Test - Target

[illegible]

Page 201 of 284

[illegible]

[illegible]

Page 203 of 284

[illegible]

Gallery Performance Report

Proof - Test - Target

Page 204 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions					1							

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: H163
Comment: ingalry:
broken trigger

Gallery Performance Report

Summary	Total Tested	686	Test Date:
	Total Rejected:	33	
	Overall Reject Rate:	4.81	

Proof	Shot:	405	18	18	97	73	28						
	Rejected:	4	0	0	0	1	1	0	0	0	0	0	0
	Percent:	1.0	0.0	0.0	0.0	1.4	3.6						
Test	Shot:	404	18	79	85	26	56						
	Rejected:	22	0	1	2	2	0	0	0	0	0	0	0
	Percent:	5.4	0.0	1.3	2.4	7.7	0.0						
Target	Shot:	38	2	8	9	3	96						
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0	0.0						

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches				1								
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Gallery Performance Report

Proof - Test - Target

[illegible]

639	6	0.9
	0	

18	686
0	27
0.0	3.9

156	0	0.0
-----	---	-----

[illegible]

Page 210 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	4				1							
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof					1							
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Proof - Test - Target

Cell: D89
Comment: ingairy:
11- 338 lapua- box fell out

Gallery Performance Report

Summary	Total Tested	541	Test Date:
	Total Rejected:	21	
	Overall Reject Rate:	3.88	

Proof	Shot:	190	49	129	84	24	19	37					
	Rejected:	3	0	0	0	0	0	0	0	0	0	0	0
	Percent:	1.6	0.0	0.0	0.0	0.0	0.0	0.0					
Test	Shot:	187	49	146	79	24	19	37					
	Rejected:	5	0	9	2	1	0	1	0	0	0	0	0
	Percent:	2.7	0.0	6.2	2.5	4.2	0.0	2.7					
Target	Shot:	19	6	15	8	4	19	4					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0	0.0	0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches			1									
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard							1					
CLM	Can't load magazine				2								
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 219 of 284

[illegible]

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof			Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face	2											
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup	1											
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	606	Test Date:
	Total Rejected:	26	
	Overall Reject Rate:	4.29	

Proof	Shot:	171	40	218	58	73		52					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0	0.0	0.0					
Test	Shot:	191	40	218	58	73		26					
	Rejected:	17	0	0	1	7	0	1	0	0	0	0	0
	Percent:	8.9	0.0	0.0	1.7	9.6		3.8					
Target	Shot:	18	5	2	2	7		3					
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:	0.0	0.0	0.0	0.0	0.0		0.0					

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches	1											
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine	8				1							
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 227 of 284

[illegible]

	2
	3
	1
	1
	2
	1
	1

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

Gallery Performance Report

Proof - Test - Target

Page 232 of 284

[illegible]

Gallery Performance Report

Summary	Total Tested	468	Test Date:
	Total Rejected:	21	
	Overall Reject Rate:	4.49	

Proof	Shot:	259	23	100		18	28	41		
	Rejected:	1	0	0	0	0	0	0	0	0
	Percent:	0.4	0.0	0.0		0.0	0.0	0.0		
Test	Shot:	258	23	74		18	28	87		
	Rejected:	12	5	0	0	0	1	2	0	0
	Percent:	4.7	21.7	0.0		0.0	3.6	3.0		
Target	Shot:	24		3		2	27	7		
	Rejected:	0	0	0	0	0	0	0	0	0
	Percent:	0.0		0.0		0.0	0.0	0.0		

CODE	MALFUNCTION INDEX	700 SPS	700 SPS	SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750
AB	Action binds										
BABS	Bulge at body shoulder										
BAC	Burr at chamber										
BBMA	BBL-to-bolt misalignment										
BB	Bolt binds/catches	3						1			
BCOAB	Bolt catches on anti-bind										
BCOBS	Bolt catches on bolt stop										
BCOF	Bolt catches on follower										
BC	Blows cases										
BHR	Bolt hits receiver										
BHS	Bolt plug hits safety switch										
BLOP	Bar lock or disconnecter out of position										
BLSO	Barrel lug shot off										
BPO	Bolt pulls out										
BSSM	Bolt stems shell in magazine										
BWCD	Bolt won't cam down										
BWCFM	Bolt won't close over full magazine										
CD	Case dented										
CH	Closes hard										
CLM	Can't load magazine										
CO	Cut-off										
CR	Cuts rim										
CS	Cases swell										
CTOG	Chamber torn or gouged										
CTP	Creepy trigger pull										
CWSB	Cams wrong side of action bar										
DBB	Doesn't blow back										
DCS	Double click in safety switch										
DCT	Double click in trigger										
DCU	Doesn't close-up										
DE	Doesn't eject										

Proof - Test - Target

[illegible]

Page 235 of 284

				Proof - Test - Target					
DEL	Doesn't eject live round								
DFB	Doesn't feed back								
DFU	Doesn't feed up								
DLO	Doesn't lock open (after last shell)								
DLU	Doesn't lock-up								
DS	Dead safe								
DX	Doesn't extract		5					1	
DXL	Doesn't extract live round								
EDS	Extractor drops shell								
ESB	Ejector sticks back								
ESCR	Empty shell catches receiver								
ESS	Extractor stems shell								
FA	Fires automatically								
FB	Follower binds								
FC	Fails to connect								
FCB	Fore-end cracked or broken								
FD	Follows-down								
FF	Fails to fire								
FFP	Flat firing pin								
FOS	Fires on safe								
FPHB	Firing pin hits bbl								
FPHI	Firing pin hits inside rim								
FPO	Floor plate opens								
FPOH	Floor plate opens hard								
FSR	Fires when safe is released								
FT	Follower tips								
GCSO	Gas cyl shot off								
HBL	Heavy bolt lift		2						
HMSC	Heading mismatch-steps on case								
HPA	High pressure ammo								
HUR	Hard under rail								
JCS	Jumps cartridge								
JM	Jumps magazine								
JO	Jars off								
LB	Light blow								
MAH	Magazine assembles hard								
MCW	Magazine capacity wrong								
MFA	Misfires (ammo)								
MFOP	Magazine follower out of position								
ML	Magazine loose								
MLH	Magazine loads hard								
MRH	Magazine removes hard								
OH	Opens hard								
OR	Over-rides								
PH	Pulls hard								
PSI	Proof stamp illegible								
PSM	Proof stamp missing								
RBOC	Rings and bulges on case								
RDW	(Action) release doesn't work								

[illegible]

Gallery Performance Report

RIC	Rings in chamber			Proof - Test - Target						
RIS	Ring in sholder									
RS	Rim srem									
SBC	Stems bottom chambers									
SBE	Stems bbl extension									
SCB	Stock cracked or broken									
SCX	Shell catches									
SHI	Short indent									
SI	Stems Incline									
SIC	Stems in chamber							1		
SL	shaves lead									
SLC	Stems left side of chamber									
SMOC	Stretch marks on case									
SOR	Stem over-ride	4								
SP	Stems port									
SR	Shoulder rough									
SRC	Stems right side of chamber									
SRIC	Specific rings in chamber									
SSOC	Surface scratches on case									
STC	Stems top chamber	3								
SWE	Safety switch works too easily									
SWH	Safety switch works too hard									
SWW	Safety Switch won't work									
TD	Tips down									
TU	Tips up									
TWP	Trigger won't pull									
TWR	Trigger won't retract									
UNCN-T	Uncoded									
XH	Extracts hard									
HI	High									
LO	Low									
LEFT	Left									
RIGHT	Right									
DG	Doesn't Group									
FSST	Front sight tipped									
RSTT	Rear sight tipped									
RBBR	Rear sight base raised									
FSTR	Front sight raised									
FSTL	Front sight loose									
RSTL	Rear sight loose									
MGPT-G	Missing parts at target									
UNCN-G	Uncoded nonconformity at target									
AI-P	Assembly incomplete at proof									
BBB	Barrel bracket cracked or broken at proof									
BC-P	Blows cases at proof									
BEB-P	Barrel extension broken at proof									
BLP-P	Blanked primer at proof									

[illegible]

Gallery Performance Report

BLSO-P	Barrel lug shot off at proof			Proof - Test - Target						
BP-P	Blown primer at proof									
BS-P	Barrel split at proof									
DBF-P	Damaged Bolt Face	1								
DLOS-P	Doesn't lock over shells at proof									
ESBBP-P	Ejector sticks back - Blown Primer cup									
ESBEC-P	Ejector sticks back - Ejector Cresent									
FCB-P	Fore-end cracked at proof									
FESO-P	Fore-end shot off at proof									
FF-P	Fails to fire at proof									
GCSO-P	Gas cylinder shot off at proof									
MSI-P	Magnaflux stamp illegible on bbl									
MSM-P	Magnaflux stamp missing on bbl									
PP-P	Pierced primer at proof									
SCB-P	Stock cracked or broken at proof									
UNCM-P	Uncoded proof malfunctions									

Gallery Performance Report

Proof - Test - Target

Page 240 of 284

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

SUBJECT TO PROTECTIVE ORDER - KINZER V. REMINGTON

BARBER - RE 0007681

[illegible]

Page 245 of 284

Gallery Performance Report

Proof - Test - Target

Page 246 of 284

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

Gallery Performance Report

Proof - Test - Target

Page 248 of 284

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

[illegible]

Page 251 of 284

[illegible]

[illegible]

Page 253 of 284

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

[illegible]

SUBJECT TO PROTECTIVE ORDER - KINZER V. REMINGTON

BARBER - RE 0007697

[illegible]

Gallery Performance Report

[illegible]

[illegible]

Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target									
BLSO-P	Barrel lug shot off at proof													
BP-P	Blown primer at proof													
BS-P	Barrel split at proof													
DBF-P	Damaged Bolt Face													
DLOS-P	Doesn't lock over shells at proof													
ESBBP-P	Ejector sticks back -Blown Primer cup													
ESBEC-P	Ejector sticks back - Ejector Cresent													
FCB-P	Fore-end cracked at proof													
FESO-P	Fore-end shot off at proof													
FF-P	Fails to fire at proof													
GCSO-P	Gas cylinder shot off at proof													
MSI-P	Magnaflux stamp illegible on bbl													
MSM-P	Magnaflux stamp missing on bbl													
PP-P	Pierced primer at proof													
SCB-P	Stock cracked or broken at proof													
UNCM-P	Uncoded proof malfunctions													

Gallery Performance Report

Proof - Test - Target

Page 264 of 284

[illegible]

Gallery Performance Report

Summary	Total Tested	0	Test Date:
	Total Rejected:	0	
	Overall Reject Rate:		

Proof	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Test	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												
Target	Shot:												
	Rejected:	0	0	0	0	0	0	0	0	0	0	0	0
	Percent:												

CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7	XR-100	750	7400	7600	7615
AB	Action binds												
BABS	Bulge at body shoulder												
BAC	Burr at chamber												
BBMA	BBL-to-bolt misalignment												
BB	Bolt binds/catches												
BCOAB	Bolt catches on anti-bind												
BCOBS	Bolt catches on bolt stop												
BCOF	Bolt catches on follower												
BC	Blows cases												
BHR	Bolt hits receiver												
BHS	Bolt plug hits safety switch												
BLOP	Bar lock or disconnecter out of position												
BLSO	Barrel lug shot off												
BPO	Bolt pulls out												
BSSM	Bolt stems shell in magazine												
BWCD	Bolt won't cam down												
BWCFM	Bolt won't close over full magazine												
CD	Case dented												
CH	Closes hard												
CLM	Can't load magazine												
CO	Cut-off												
CR	Cuts rim												
CS	Cases swell												
CTOG	Chamber torn or gouged												
CTP	Creepy trigger pull												
CWSB	Cams wrong side of action bar												
DBB	Doesn't blow back												
DCS	Double click in safety switch												
DCT	Double click in trigger												
DCU	Doesn't close-up												

Proof - Test - Target

[illegible]

Page 267 of 284

[illegible]

[illegible]

Page 269 of 284


[illegible]


[illegible]


Gallery Performance Report

BLP-P	Blanked primer at proof				Proof - Test - Target								
BLSO-P	Barrel lug shot off at proof												
BP-P	Blown primer at proof												
BS-P	Barrel split at proof												
DBF-P	Damaged Bolt Face												
DLOS-P	Doesn't lock over shells at proof												
ESBBP-P	Ejector sticks back -Blown Primer cup												
ESBEC-P	Ejector sticks back - Ejector Cresent												
FCB-P	Fore-end cracked at proof												
FESO-P	Fore-end shot off at proof												
FF-P	Fails to fire at proof												
GCSO-P	Gas cylinder shot off at proof												
MSI-P	Magnaflux stamp illegible on bbl												
MSM-P	Magnaflux stamp missing on bbl												
PP-P	Pierced primer at proof												
SCB-P	Stock cracked or broken at proof												
UNCM-P	Uncoded proof malfunctions												

[illegible]







AB	Action binds	0
BABS	Bulge at body shoulder	0
BAC	Burr at chamber	0
BBMA	BBL-to-bolt misalignment	0
BB	Bolt binds/catches	0
BCOAB	Bolt catches on anti-bind	0
BCOBS	Bolt catches on bolt stop	0
BCOF	Bolt catches on follower	0
BC	Blows cases	0
BHR	Bolt hits receiver	0
BHS	Bolt plug hits safety switch	0
BLOP	Bar lock or disconnecter out of position	0
BLSO	Barrel lug shot off	0
BPO	Bolt pulls out	0
BSSM	Bolt stems shell in magazine	0
BWCD	Bolt won't cam down	0
BWCFM	Bolt won't close over full magazine	0
CD	Case dented	0
CH	Closes hard	0
CLM	Can't load magazine	0
CO	Cut-off	0
CR	Cuts rim	0
CS	Cases swell	0
CTOG	Chamber torn or gouged	0
CTP	Creepy trigger pull	0
CWSB	Cams wrong side of action bar	0
DBB	Doesn't blow back	0
DCS	Double click in safety switch	0
DCT	Double click in trigger	0
DCU	Doesn't close-up	0
DE	Doesn't eject	0
DEL	Doesn't eject live round	0
DFB	Doesn't feed back	0
DFU	Doesn't feed up	0
DLO	Doesn't lock open (after last shell)	0
DLU	Doesn't lock-up	0
DS	Dead safe	0
DX	Doesn't extract	0
DXL	Doesn't extract live round	0
EDS	Extractor drops shell	0
ESB	Ejector sticks back	0
ESCR	Empty shell catches receiver	0
ESS	Extractor stems shell	0
FA	Fires automatically	0
FB	Follower binds	0
FC	Fails to connect	0
FCB	Fore-end cracked or broken	0
FD	Follows-down	0
FF	Fails to fire	0

FFP	Flat firing pin	0
FOS	Fires on safe	0
FPHB	Firing pin hits bbl	0
FPHI	Firing pin hits inside rim	0
FPO	Floor plate opens	0
FPOH	Floor plate opens hard	0
FSR	Fires when safe is released	0
FT	Follower tips	0
GCSO	Gas cyl shot off	0
HBL	Heavy bolt lift	0
HMSC	Heading mismatch-steps on case	0
HPA	High pressure ammo	0
HUR	Hard under rail	0
JCS	Jumps cartridge	0
JM	Jumps magazine	0
JO	Jers off	0
LB	Light blow	0
MAH	Magazine assembles hard	0
MCW	Magazine capacity wrong	0
MFA	Misfires (ammo)	0
MFOP	Magazine follower out of position	0
ML	Magazine loose	0
MLH	Magazine loads hard	0
MRH	Magazine removes hard	0
OH	Opens hard	0
OR	Over-rides	0
PH	Pulls hard	0
PSI	Proof stamp illegible	0
PSM	Proof stamp missing	0
RBOC	Rings and bulges on case	0
RDW	(Action) release doesn't work	0
RIC	Rings in chamber	0
RIS	Ring in sholder	0
RS	Rim srem	0
SBC	Stems bottom chambers	0
SBE	Stems bbl extension	0
SCB	Stock cracked or broken	0
SCX	Shell catches	0
SHI	Short indent	0
SI	Stems incline	0
SIC	Stems in chamber	0
SL	shaves lead	0
SLC	Stems left side of chamber	0
SLOC	Stretch marks on case	0
SOR	Stem over-ride	0
SP	Stems port	0
SR	Shoulder rough	0
SRC	Stems right side of chamber	0
SRIC	Specific rings in chamber	0

SSOC	Surface scratches on case	0
STC	Stems top chamber	0
SWE	Safety switch works too easily	0
SWH	Safety switch works too hard	0
SWW	Safety Switch won't work	0
TD	Tips down	0
TU	Tips up	0
TWP	Trigger won't pull	0
TWR	Trigger won't retract	0
UNCN-T	Uncoded	0
XH	Extracts hard	0
		0
HI	High	0
LO	Low	0
LEFT	Left	0
RIGHT	Right	0
DG	Doesn't Group	0
FSST	Front sight tipped	0
RSTT	Rear sight tipped	0
RSBR	Rear sight base raised	0
FSTR	Front sight raised	0
FSTL	Front sight loose	0
RSTL	Rear sight loose	0
MGPT-G	Missing parts at target	0
UNCN-G	Uncoded nonconformity at target	0
		0
AI-P	Assembly incomplete at proof	0
BBB	Barrel bracket cracked or broken at proof	0
BC-P	Blows cases at proof	0
BEB-P	Barrel extension broken at proof	0
BLP-P	Blanked primer at proof	0
BLSO-P	Barrel lug shot off at proof	0
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DBF-P	Damaged Bolt Face	0
DLOS-P	Doesn't lock over shells at proof	0
ESBBP-P	Ejector sticks back -Blown Primer cup	0
ESBEC-P	Ejector sticks back - Ejector Crescent	0
FCB-P	Fore-end cracked at proof	0
FESO-P	Fore-end shot off at proof	0
FF-P	Fails to fire at proof	0
GCSO-P	Gas cylinder shot off at proof	0
MSI-P	Magnaflux stamp illegible on bbl	0
MSM-P	Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	0
SCB-P	Stock cracked or broken at proof	0

AB	Action binds	0
BABS	Bulge at body shoulder	0
BAC	Burr at chamber	0
BBMA	BBL-to-bolt misalignment	0
BB	Bolt binds/catches	0
BCOAB	Bolt catches on anti-bind	0
BCOBS	Bolt catches on bolt stop	0
BCOF	Bolt catches on follower	0
BC	Blows cases	0
BHR	Bolt hits receiver	0
BHS	Bolt plug hits safety switch	0
BLOP	Bar lock or disconnecter out of position	0
BLSO	Barrel lug shot off	0
BPO	Bolt pulls out	0
BSSM	Bolt stems shell in magazine	0
BWCD	Bolt won't cam down	0
BWCFM	Bolt won't close over full magazine	0
CD	Case dented	0
CH	Closes hard	0
CLM	Can't load magazine	0
CO	Cut-off	0
CR	Cuts rim	0
CS	Cases swell	0
CTOG	Chamber torn or gouged	0
CTP	Creepy trigger pull	0
CWSB	Cams wrong side of action bar	0
DBB	Doesn't blow back	0
DCS	Double click in safety switch	0
DCT	Double click in trigger	0
DCU	Doesn't close-up	0
DE	Doesn't eject	0
DEL	Doesn't eject live round	0
DFB	Doesn't feed back	0
DFU	Doesn't feed up	0
DLO	Doesn't lock open (after last shell)	0
DLU	Doesn't lock-up	0
DS	Dead safe	0
DX	Doesn't extract	0
DXL	Doesn't extract live round	0
EDS	Extractor crops shell	0
ESB	Ejector sticks back	0
ESCR	Empty shell catches receiver	0
ESS	Extractor stems shell	0
FA	Fires automatically	0
FB	Follower binds	0
FC	Fails to connect	0
FCB	Fore-end cracked or broken	0
FD	Follows-down	0
FF	Fails to fire	0

FFP	Flat firing pin	0
FOS	Fires on safe	0
FPHB	Firing pin hits bbl	0
FPHI	Firing pin hits inside rim	0
FPO	Floor plate opens	0
FPOH	Floor plate opens hard	0
FSR	Fires when safe is released	0
FT	Follower tips	0
GCSO	Gas cyl shot off	0
HBL	Heavy bolt lift	0
HMSC	Heading mismatch-steps on case	0
HPA	High pressure ammo	0
HUR	Hard under rail	0
JCS	Jumps cartridge	0
JM	Jumps magazine	0
JO	Jers off	0
LB	Light blow	0
MAH	Magazine assembles hard	0
MCW	Magazine capacity wrong	0
MFA	Misfires (ammo)	0
MFOP	Magazine follower out of position	0
ML	Magazine loose	0
MLH	Magazine loads hard	0
MRH	Magazine removes hard	0
OH	Opens hard	0
OR	Over-rides	0
PH	Pulls hard	0
PSI	Proof stamp illegible	0
PSM	Proof stamp missing	0
RBOC	Rings and bulges on case	0
RDW	(Action) release doesn't work	0
RIC	Rings in chamber	0
RIS	Ring in sholder	0
RS	Rim srem	0
SBC	Stems bottom chambers	0
SBE	Stems bbl extension	0
SCB	Stock cracked or broken	0
SCX	Shell catches	0
SHI	Short indent	0
SI	Stems incline	0
SIC	Stems in chamber	0
SL	shaves lead	0
SLC	Stems left side of chamber	0
SLOC	Stretch marks on case	0
SOR	Stem over-ride	0
SP	Stems port	0
SR	Shoulder rough	0
SRC	Stems right side of chamber	0
SRIC	Specific rings in chamber	0

SSOC	Surface scratches on case	0
STC	Stems top chamber	0
SWE	Safety switch works too easily	0
SWH	Safety switch works too hard	0
SWW	Safety Switch won't work	0
TD	Tips down	0
TU	Tips up	0
TWP	Trigger won't pull	0
TWR	Trigger won't retract	0
UNCN-T	Uncoded	0
XH	Extracts hard	0
		0
HI	High	0
LO	Low	0
LEFT	Left	0
RIGHT	Right	0
DG	Doesn't Group	0
FSST	Front sight tipped	0
RSTT	Rear sight tipped	0
RSBR	Rear sight base raised	0
FSTR	Front sight raised	0
FSTL	Front sight loose	0
RSTL	Rear sight loose	0
MGPT-G	Missing parts at target	0
UNCN-G	Uncoded nonconformity at target	0
		0
AI-P	Assembly incomplete at proof	0
BBB	Barrel bracket cracked or broken at proof	0
BC-P	Blows cases at proof	0
BEB-P	Barrel extension broken at proof	0
BLP-P	Blanked primer at proof	0
BLSO-P	Barrel lug shot off at proof	0
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DBF-P	Damaged Bolt Face	0
DLOS-P	Doesn't lock over shells at proof	0
ESBBP-P	Ejector sticks back -Blown Primer cup	0
ESBEC-P	Ejector sticks back - Ejector Crescent	0
FCB-P	Fore-end cracked at proof	0
FESO-P	Fore-end shot off at proof	0
FF-P	Fails to fire at proof	0
GCSO-P	Gas cylinder shot off at proof	0
MSI-P	Magnaflux stamp illegible on bbl	0
MSM-P	Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	0
SCB-P	Stock cracked or broken at proof	0

AB	Action binds	0
BABS	Bulge at body shoulder	0
BAC	Burr at chamber	0
BBMA	BBL-to-bolt misalignment	0
BB	Bolt binds/catches	0
BCOAB	Bolt catches on anti-bind	0
BCOBS	Bolt catches on bolt stop	0
BCOF	Bolt catches on follower	0
BC	Blows cases	0
BHR	Bolt hits receiver	0
BHS	Bolt plug hits safety switch	0
BLOP	Bar lock or disconnecter out of position	0
BLSO	Barrel lug shot off	0
BPO	Bolt pulls out	0
BSSM	Bolt stems shell in magazine	0
BWCD	Bolt won't cam down	0
BWCFM	Bolt won't close over full magazine	0
CD	Case dented	0
CH	Closes hard	0
CLM	Can't load magazine	0
CO	Cut-off	0
CR	Cuts rim	0
CS	Cases swell	0
CTOG	Chamber torn or gouged	0
CTP	Creepy trigger pull	0
CWSB	Cams wrong side of action bar	0
DBB	Doesn't blow back	0
DCS	Double click in safety switch	0
DCT	Double click in trigger	0
DCU	Doesn't close-up	0
DE	Doesn't eject	0
DEL	Doesn't eject live round	0
DFB	Doesn't feed back	0
DFU	Doesn't feed up	0
DLO	Doesn't lock open (after last shell)	0
DLU	Doesn't lock-up	0
DS	Dead safe	0
DX	Doesn't extract	0
DXL	Doesn't extract live round	0
EDS	Extractor drops shell	0
ESB	Ejector sticks back	0
ESCR	Empty shell catches receiver	0
ESS	Extractor stems shell	0
FA	Fires automatically	0
FB	Follower binds	0
FC	Fails to connect	0
FCB	Fore-end cracked or broken	0
FD	Follows-down	0
FF	Fails to fire	0

FFP	Flat firing pin	0
FOS	Fires on safe	0
FPHB	Firing pin hits bbl	0
FPHI	Firing pin hits inside rim	0
FPO	Floor plate opens	0
FPOH	Floor plate opens hard	0
FSR	Fires when safe is released	0
FT	Follower tips	0
GCSO	Gas cyl shot off	0
HBL	Heavy bolt lift	0
HMSC	Heading mismatch-steps on case	0
HPA	High pressure ammo	0
HUR	Hard under rail	0
JCS	Jumps cartridge	0
JM	Jumps magazine	0
JO	Jers off	0
LB	Light blow	0
MAH	Magazine assembles hard	0
MCW	Magazine capacity wrong	0
MFA	Misfires (ammo)	0
MFOP	Magazine follower out of position	0
ML	Magazine loose	0
MLH	Magazine loads hard	0
MRH	Magazine removes hard	0
OH	Opens hard	0
OR	Over-rides	0
PH	Pulls hard	0
PSI	Proof stamp illegible	0
PSM	Proof stamp missing	0
RBOC	Rings and bulges on case	0
RDW	(Action) release doesn't work	0
RIC	Rings in chamber	0
RIS	Ring in sholder	0
RS	Rim srem	0
SBC	Stems bottom chambers	0
SBE	Stems bbl extension	0
SCB	Stock cracked or broken	0
SCX	Shell catches	0
SHI	Short indent	0
SI	Stems incline	0
SIC	Stems in chamber	0
SL	shaves lead	0
SLC	Stems left side of chamber	0
SMOC	Stretch marks on case	0
SOR	Stem over-ride	0
SP	Stems port	0
SR	Shoulder rough	0
SRC	Stems right side of chamber	0
SRIC	Specific rings in chamber	0

SSOC	Surface scratches on case	0
STC	Stems top chamber	0
SWE	Safety switch works too easily	0
SWH	Safety switch works too hard	0
SWW	Safety Switch won't work	0
TD	Tips down	0
TU	Tips up	0
TWP	Trigger won't pull	0
TWR	Trigger won't retract	0
UNCN-T	Uncoded	0
XH	Extracts hard	0
		0
HI	High	0
LO	Low	0
LEFT	Left	0
RIGHT	Right	0
DG	Doesn't Group	0
FSST	Front sight tipped	0
RSTT	Rear sight tipped	0
RSBR	Rear sight base raised	0
FSTR	Front sight raised	0
FSTL	Front sight loose	0
RSTL	Rear sight loose	0
MGPT-G	Missing parts at target	0
UNCN-G	Uncoded nonconformity at target	0
		0
AI-P	Assembly incomplete at proof	0
BBB	Barrel bracket cracked or broken at proof	0
BC-P	Blows cases at proof	0
BEB-P	Barrel extension broken at proof	0
BLP-P	Blanked primer at proof	0
BLSO-P	Barrel lug shot off at proof	0
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DBF-P	Damaged Bolt Face	0
DLOS-P	Doesn't lock over shells at proof	0
ESBBP-P	Ejector sticks back -Blown Primer cup	0
ESBEC-P	Ejector sticks back - Ejector Crescent	0
FCB-P	Fore-end cracked at proof	0
FESO-P	Fore-end shot off at proof	0
FF-P	Fails to fire at proof	0
GCSO-P	Gas cylinder shot off at proof	0
MSI-P	Magnaflux stamp illegible on bbl	0
MSM-P	Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	0
SCB-P	Stock cracked or broken at proof	0