

YES YES GUN EXAMINATION REPORT NUMBER: 3 MODEL: 600
 GUN CONDITION: USED R #: 11659
 SIDE WORK: SCORE MOV - 2250 DATE: 1-5-70
 FROM: DS9 B-VSS
 GUN AND TYPE: REM-UMC CAMP COLORED
 & CONDITION: 12532
 GUN #: 12532
 COP: RED INSP.: 94 TEST: 36 CODE: PL-5-64
 BARS: 04 GA./CAL.: 222
 REAR OPENING: 04 CHECKED BY: 11-H-AGV
 SOOT SHOULDERS: 04 APPROVED: 9/15/70
 RINGS: 04 APPROVED: 9/15/70
 FEET: 04 APPROVED: 9/15/70
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 9/15/70
SLIGHT WISPER WAPS - STEEL - 2-3 DENTED
2 LT - 2 DENTED

17467 - FIREARMS 17467 DESIGNED
 COMPLAINT: FORWARD

INCIDENT: _____

COMMENTS:

See lift 007. Gun & Safety cam has
sluggish action due to gummy substance on these
parts. This condition could have contributed to incident.

Replace trigger assembly.