

GUN EXAMINATION REPORT NUMBER: 133 MODEL: 600
 & CONDITION: USED R# 10060
 THE WORK: SIGHTS AND SCOPE DATE: 6-5-70
SCREWS REMOVED FROM: 2037400
STOCK HEAD (240) 00640000
 AND BOND TYPE: NOT KNOWN GUN # 1307525
 & CONDITION: CODE: BZ = 1-75
 PROOF: (FEP) INSP.: 54 TEST: 5 GA./CAL.: 222
 HEADS: OK CHECKED BY: NI - H 4704
 BREWER OPENED: OK APPROVED: 90H 6/27/80
 RECOIL SHOULDERS: OK APPROVED: 90H 6/27/80
 CHAMBER: CITY APPROVED: 90H 6/27/80
 TEST: APPROVED: 90H 6/27/80
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 90H 6/27/80
BRIGHT METAL IN BBL AND 10000 WEPS

COMPLAINT: GOES OFF AS BOLT IS
LOCKED FORWARD

INCIDENT: _____

COMMENTS:

Die control & adjusted outside factory - trigger
adjusting and overtravel screws are not sealed.
Trigger connector broken possibly from improper
adjustment of screws.
Gun was involved in recall - Repair at no charge.

1 year repair at no charge - 9/80