

BARBER - RE 0011747

Accidental discharge model 700 BDL

Discussion Thread

Response (Norm) 5/14/2007 6:22:30 AM

Dear Barry:

Thank you for visiting Remington Country. What is the serial number of the gun? Has the trigger been adjusted or cleaned recently? When and where did you have the safety modification done?

Customer (Barry Mayfield) 5/12/2007 11:31:33 PM

Recently I was preparing to unload my my model 700 BDL 30-06. I had had the safety modifiaction done so that I could open the bolt on a loaded chamber with the safety on. By old habit I placed the safety in the fire position. As I rotated the bolt the rifle fired. Luckily it was pointed in a safe direction. Any recomendations or explanations as to why this may have happened. The rifle is about 15 years old and The bolt assembly was cleaned when the safety modification was done

BARBER - RE 0011747

RE0011687