

BARBER - RE 0011808

model 700 trigger/safety misfires

Discussion Thread

Response (Tan) 12/6/2008 7:29:27 AM

Dear Mr. Siepietowski,

We regret you are experiencing a problem with your Model 700. We would like to speak to you in more detail regarding your inquiry. If you will please contact our Parts & Repair Department with your SERIAL NUMBER, at 1-800-243-9700 Mon-Fri 9-5 EST, our representatives can assist you with this matter.

Customer (Gary Siepietowski) 12/2/2008 3:53:11 PM

I have a model 700 in 7mm-08, that has approx. 5 years under its belt and has performed flawlessly. At the range the other day the rifle fired when the safety was moved from QUOTEsafeQUOTE to QUOTEfireQUOTE on the bench. Further investigation found that the safety cannot be moved to safe without opening the bolt. I also could replicate the QUOTEmisfireQUOTE by apply the smallest amount of pressure to the trigger prior to moving the safety to fire. I need advice from Remington as this appears to be a malfunction that should not happen and I believe that there is some history of this problem with the trigger/safety group. Please advise....Gary Siepietowski 610-369-7858

BARBER - RE 0011808

RE0011748