

P.I. NO GUN EXAMINATION REPORT NUMBER: 530 MODEL: 700 BDL
GENERAL CONDITION: FAIR R #: 24180
OUTSIDE WORK: S/REMOVED, SCOPE MOUNTS ADDED DATE: 10-9-81
TRIG & CONNECTOR REMOVED AS IS FROM: BILLY W. SWEAT
FIRE ARM TYPE: NOT KNOWN PT-2 EX 1064
& CONDITION: ALLEN TSV TEN.
PROCP: 1 INSP.: 123 TEST: 64 GUN #: A6376164
READING: OK CODE: RI-11-76
BREACH OPENING: OK CAL./CAL.: 6MM REM
RECOIL SHOULDERS: OK CHECKED BY: M-HARDY
CLAMBER: OK APPROVED: 90st 10/21/81
TEST: CHECKED FIRE PIN PROTRUSION, OK APPROVED: PR 10/21/81
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 10/21/81
TRIG CONNECTOR BROKEN APPROVED: 10-23-81

COMPLAINT: FIRE WHEN TAKEN OFF SAFETY

INCIDENT: _____

COMMENTS: _____

Please replace fire control - no charge
Sgt

RECEIVING and ESTIMATE REPORT

NO. 122 ORDER R 24180

DATE 10-9-81 ESTIMATED 11/17/81 VIA UP CHARGES NOV 18 1981

FROM Billy W. Sweet

Rt 2, Box 1861, Alleyton, Tex.

DEL and GRADE 700BXL 6mm Rem. SERIAL NO A6376164 DATE RI

GRADE CODE 11-76

COMPUTER REPR. ONLY u/ Scope mt., L/sights REPAIR CHG 512-75

INS.

Gun Damaged PARCEL POST

CONDITION (New) (Slightly worn) (Very worn) (Misused) (Overset) TOTAL

TOWNER'S COMPLAINT Trigger Malfunction

NO FAULT Trigger Computer Broken

GALLERY REPORT

26655 Trigger Hammer Action

Partial Chamber

Link Done

287

NOV 25 1981

Gentlemen

Please Replace And/or Repair the
Trigger Assy on this Rem 700 BDL.
Ser. # A 6376 164.

My original problem was that the
Rifle would sometimes fire when taken
off safety. Upon examination I found
that the trigger connector would sometimes
hang point to point on the sear. This
would allow it to fire when taken off safety.

Thank you

Bill W. Stewart
Rt 3 Box 136 A
Allamore, Texas 76935

5 74 043 08-02-21964

JBH