

P.I. NO GUN EXAMINATION REPORT NUMBER: 644 MODEL: 700 ADL
GENERAL CONDITION: FAIR R #: 08105
OUTSIDE WORK: SCOPE SCREWS REMOVED DATE: 2-18-82
JEWEL STOPS ADDED FROM: J.E. CHRISTEN
FIRED AMMO TYPE: NOT KNOWN 575 LAUREL LAKE
& CONDITION: LANCASTER PA GUN #: 6475149
PROOF: M INSP.: ? TEST: 13 CODE: DU = 9-71
HEADING: OK GA./CAL.: 3006
BREECH OPENING: OK CHECKED BY: M. HARDY
RECOIL SHOULDERS: OK APPROVED: JPH 3/16/82
CHAMBER: OK APPROVED: P.N. 3/16/82
TEST: OK 3/16/82 APPROVED: JPH 3/16/82
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: J
SLIGHT NIPS ON STOCK. BOLT RELEASE BINDS

COMPLAINT: FIRING ON TWO OCCASIONS WHEN SAFETY
WAS MOVED TO FIRE POS. BOTH TIMES CHAMBER WAS EMPTY
INCIDENT: _____

COMMENTS: Apparent cause of malfunction due to jammed
up fire control.
.002 Seal lift
.070 Seal engagement.
OK on trick test.

RECEIVING and RETURN REPORT

ORDER R08687

Remington.

cc: J.H. Chiswell

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE 612 894-7961

March 10, 1982 *file*

J E Christensen
576 Laurel Lane
Lancaster, Pa 17601

Model 700
Repair Order R-8105
Ref: Your letter

Dear Sir:

This will acknowledge receipt of the above arm.

The gun is being checked by our Engineering Division and promptly upon completion of their examination, we will advise you.

We appreciate very much this opportunity to be of service.

Cordially,

Dennis Sanita

Supervisor
ARMS SERVICE DIVISION

DJS:jr

RECEIVING and ESTIMATE REPORT

ORDER R 08105

RQM. DATE 3-1-82
RECEIVED 11/13 ESTIMATED 11/13 VIA 11P CHARGESFROM J. L. Christensen116 Laurel Ln. Lancaster, Pa 17601MODEL and GRADE 1003106

SERIAL NO.

61751-1

DATE

CODE

00GRADE
CODE7-71

OR COMPUTER REPR. ONLY

REPAIR CHO.

INS.

PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quoted)

TOTAL

CUSTOMER'S COMPLAINT

MAIN FAULT

GALLERY REPORT

DESCRIPT
CODE

Clean (Low) (Target)

Signature

DON'T SAY IT-WRITE IT

cc: K.D. Green

To D.J. SANITA Location ARMS SERVICE 52-2
From J.A. STEKL Location PRODUCT SERVICE 52-4 Phone
Subject R#08105 M/700 ADL 30-06 CALIBER RIFLE, SERIAL #6475149 No. 3/18/82

Please replace the trigger assembly on the subject rifle and clean the gummy substance off the receiver and barrel, at no-charge and return to:

Mr. J.E. Christensen
576 Laurel Lane
Lancaster, Pa. 17601

Please expedite the work.

Thank you,

J.A. Stekl
JAS:tpv

RD 778

STOP, LOOK, AND LIVE

P.I. NO GUN EXAMINATION REPORT NUMBER: 644 MODEL: 700 ADL
 GENERAL CONDITION: FAIR R #: 08105
 OUTSIDE WORK: SCOPE SCREENS REMOVED DATE: 2-18-82
SWIVEL STUDS ADDED FROM: J.E. CHRISTEN
576 LAUREL LAVE
LANCASTER PA
 FIRED AMMO TYPE: NOT KNOWN GUN #: 6475149
 & CONDITION: _____ CODE: DU = 9-71
 PROOF: M INSP.: ? TEST: 13 GA./CAL.: 3006
 HEADING: OK CHECKED BY: M. HARDY
 BREECH OPENING: OK APPROVED: JPH 3/16/82
 RECOIL SHOULDERS: OK APPROVED: P.N. 3/16/82
 CHAMBER: OK APPROVED: PH 3/16/82
 TEST: _____ APPROVED: 1
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
SLIGHT MARKS ON STOCK. BOLT RELEASE BINDS

COMPLAINT: FIRING ON TWO OCCASIONS WHEN SAFETY
WAS MOVED TO FIRE POS. BOTH TIMES CHAMBER WAS EMPTY

INCIDENT: _____

COMMENTS: Apparent cause of malfunction due to jammed
up fire control.
.008 Sear lift
.070 Sear engagement.
OK on track test.