

P.I. YES GUN EXAMINATION REPORT NUMBER: 74 MODEL: 700-LH BDL
 GENERAL CONDITION: FAIR R #: 02021
 OUTSIDE WORK: SIGHTS REMOVED ALSO DATE: 1-11-79
SCOPE SCREWS FROM: W. BARGAIN STORE
WHITAKER + TILLEY'S
ENFIELD N.C.
 FIRED AMMO TYPE: UNKNOWN GUN #: 6627846
 & CONDITION: — CODE: W-K-8-73
 PROOF: CRIP B INSP.: 73 TEST: 111 GA./CAL.: 270
 HEADING: OK CHECKED BY: M. HARDY
 BREECH OPENING: OK APPROVED: 3/2/79
 RECOIL SHOULDERS: OK APPROVED: 3/2/79
 CHAMBER: OK APPROVED: 3/2/79
 TEST: — APPROVED: 3/2/79
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 3-2-79

SMALL DENTS IN WOOD BOLT SHOULDER WENT
BRIGHT METAL ON BBL.

COMPLAINT: FIRE WHEN SAFETY IS RELEASED

INCIDENT: BULLET HOLE THROUGH FLOOR BOARD &
TRANSMISSION OF TRUCK

COMMENTS: Trigger pull adjusted below factory specs.
Trigger adjusting screw appears to have been
adjusted outside factory. No return spring tension
on trigger.

HOLD FOR REPLY FROM J. H. CHISNALL

March 7, 1979
Elton, N. Y. 13357

TO: J. H. CHISNALL

FROM: D. J. SANITA

Model 700 Rifle 6627846
Repair Order R-2021-700

Dear Jack,

We have completed our examination of the above subject Model 700, which was received from New York Bargain Store.

For completion of your files, we are attaching a gun examination report and the customer's correspondence. There were no photographs taken of the arm.

Due to the reference of a product liability, we will hold the above and await your reply as to its disposition.

Best regards,

D. J. Sanita:cm
Attach.

Arms Service Division, Supervisor

RECEIVING and ESTIMATE REPORT

ORDER R 02021

FROM DATE

RECEIVED

1-11-79

ESTIMATED

4-23-79

VIA

Wp

CHARGES

APR 24 1979

FROM

NEW YORK BARGAIN STORE

CORNER WHITAKER & TIMEY ST. ENFIELD, N.C.

MODEL and GRADE

700LH BDL 270WIN

SERIAL NO.

6627846

DATE

CODE

WX

GRADE
CODE

8-73

FOR COMPUTER REFER. ONLY

REPAIR CHG

INS.

PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quote)

TOTAL

CUSTOMER'S COMPLAINT

INSTALL NEW TRIGGER ASSEM

MAIN FAULT

Trigger adjusting screws adjusted outside of flange.

GALLERY REPORT

DEMERIT
CODE

(Clean) (Test) (Target)

Repairman

APR 25 1979