

P.I. YES GUN EXAMINATION REPORT NUMBER: 48 MODEL: 700
GENERAL CONDITION: FAIR R #: 00557
OUTSIDE WORK: SCOPE MOUNTS ADDED DATE: 12/27/78
FROM: DEB. GEIER
FIRED AMMO TYPE: UNKNOWN BUL 228 P&T LATCH 10AM
& CONDITION: _____ GUN #: 6771922
PROOF: CRP INSP.: 41 TEST: 70 CODE: 04-7-74
HEADING: OK GA./CAL.: 3006
BREECH OPENING: OK CHECKED BY: MI-4-804
RECOIL SHOULDERS: OK APPROVED: 1/12/79
CHAMBER: RUSTY APPROVED: 1/12/79
TEST: _____ APPROVED: 7-12-79
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 1-12-79
STOCK DENTED, COLOR OFF BAL. RUSTY REC.

COMPLAINT: FIRED WHEN SAFETY WAS RELEASED

INCIDENT: P&T HOLE IN CARPET AND FLOOR

COMMENTS: Unable to duplicate customer's malfunction
all components within factory specs

F.D. 0010-
R-29285

February 6, 1979

Ms. Deb Geier
Box 228
Potlatch, Idaho 83855

Dear Ms. Geier:

Examination has been completed on your Model 700 BDL, 30-06 caliber rifle, serial number 6771922, which allegedly fired when the safety was pushed to the off position.


Our experts thoroughly examined the rifle and trigger assembly and could not duplicate the incident you have described. All parts tolerances and dimensions were found to be normal, including sear-connector engagement. Also, factory seals were intact on the trigger adjustment screws, indicating no alterations were made to the trigger outside of our Company.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for this incident. We can only assume that as the safety was pushed to the off position, contact was made with the trigger. When the safety is in the on safe position, the sear is lifted off of the trigger connector. At this time, very little effort is required to pull the trigger rearward, allowing the connector to be moved away from under the sear and, in this condition, on moving the safety to the off position, the rifle will fire.

We trust that we have clarified the circumstances that could possibly have caused the accidental firing and, as a gesture of good will, even though there is nothing wrong with your present trigger assembly, we can replace it with another assembly, at no charge, to insure that your faith in your rifle is restored, or, the rifle can be returned as received. We will await your decision and reply.

Thank you for having afforded us the opportunity to examine your rifle and to be of service.

Sincerely,


E.F. Sienkiewicz, Supervisor
Firearms Product Service

EFS:tp

GENERAL CONDITION: FAIR

OUTSIDE WORK: SCOPE MOUNTS ADDED

FIRE AMMO TYPE: UNKNOWN

& CONDITION: _____

PROOF: CRP INSP.: 41 TEST: 70

HEADING: OK

BREECH OPENING: OK

RECOIL SHOULDERS: OK

CHAMBER: RUSTY

TEST: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

STOCK DENTED, COLOR OFF BBL, RUSTY REC.

COMPLAINT: FIRE WHEN SAFETY WAS RELEASED

INCIDENT: PUT HOLE IN CARPET AND FLOOR

COMMENTS: Unable to duplicate customer's malfunction
all components within factory specs

DATE: 12/27/78

FROM: DEB GEIER

BOX 228 POTLATCH IDAHO

GUN #: 6771922

CODE: 0Y-7-74

GA./CAL.: 3006

CHECKED BY: M-HARDY

APPROVED: 1/12/79

APPROVED: 1/12/79

APPROVED: 1-12-79

APPROVED: 1-12-79

P.B. 1-12-79

Mr. Sienkiewicz -

12-10-18

This Remington 30.6
(model 700) has fired when
the safety was released.
The gun was loaded, the
trigger was not bumped, squeezed,
or pulled... (nor was the gun)

As a result, our carpet
& floor now has a hole
in it. I figure \$50.00
would compensate for damages
& repairs.

I do hope the gun can
be fixed.

Thank you.
Deb Geier
Box 228
Potlatch
Idaho
83855

phone #
208) 875 0304

2/27/78

DEB GEIER

28 POTLATCH IDAHO

6771922

04-7-74

3006

D BY: M-HARDY

ED: 1/12/79

VED: 1/12/79

VED: 1-12-79

VED: 1-12-79

RUSTY REC.

EASED

LOOP

malfunction

R.B. 1-12-79

RECEIVING and ESTIMATE REPORT

ORDER R 00557

FROM DATE

RECEIVED

12-27-78

ESTIMATED

2-16-79

VIA

INS 743162

CHARGES

FEB 10 1979

FROM

DEB

GCIER

Box 228

POTLATCH

IDaho

MODEL and GRADE

700 BDL

30-06 SPN

SERIAL NO.

6771922

DATE

CODE

04

GRADE
CODE

7-74

FOR COMPUTER REFER. ONLY

W/SCOPE mts.

REPAIR CHG.

80-55

INS.

PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quite)

TOTAL

CUSTOMER'S COMPLAINT

In Stall new

TRIGGER Assm

MAIN FAULT

Rifle Fired when Safety was released.
Shot a hole in the carpet.Unable to duplicate customer's malfunction
All components within factory specs

GALLERY REPORT

DEMERIT
CODE

Polish chamber

26345- Trig housing anem

Work Done

(Clean) (Test) (Target)

Repairman

FEB 22 1979