

P.I. YES GUN EXAMINATION REPORT NUMBER: 307 MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 33285
 OUTSIDE WORK: NONE DATE: 12-8-80
 FROM: CENTRAL GUN SHOP
124 E WALL ST
 FIRED AMMO TYPE: NOT KNOWN FT SCOTT K&N.
 & CONDITION: _____ GUN #: B6229768
 PROCP: (R/P) INSP.: 131 TEST: 119 CODE: PA = 6-80
 HEADING: OK GA./CAL.: 7MM REM MAG
 BREACH OPENING: OK CHECKED BY: M-HARDY
 RECOIL SHOULDERS: OK APPROVED: 9/21/81
 CHAMBER: OK APPROVED: 11/2/81
 TEST: _____ APPROVED: 11/2/81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

BRIGHT MARK ON LEFT SIDE OF TRIG. GUARD

COMPLAINT: FIRED WHEN SAFE WAS RELEASED

Attended by itself when he let of the safety setting
hole in his friends truck door!

INCIDENT: _____

COMMENTS: _____

Trigger pull 5#, Rifle passed tick test.
Unable to duplicate customer complaint.

RECEIVING and ESTIMATE REPORT

FROM DATE

2/16

ORDER R 33285

RECEIVED

12/8/80

ESTIMATED

2-6-81

VIA

JP

CHARGES

FEB 09 1981

FROM

C G S

(50877)

124 E WALL

FT SCOTT

KAN

MODEL and GRADE

700 BDL / 7mm REM MING

SERIAL NO.

BG229768

DATE

CODE

P/A

GRADE
CODE

G/80

FOR COMPUTER REPR. ONLY

W/ SW - SCING

REPAIR CHG.

80-55

INS.

PARCEL POST

GUN CONDITION: (New) (Slightly worn) (Very worn) (Misused) (Other)

TOTAL

CUSTOMER'S COMPLAINT

Fired when safety was pushed off

MAIN FAULT

Fired when safety was pushed off

Fired when safety was pushed off

GALLERY REPORT

GALLERY
CODE

2/6/81 - Trigger throwing off

FEB 10 1981

No. 508977
 134 E WALL
 CITY/STATE ZIP 67201
 DATE 11-28-80 SHIP VIA UPS
 FROM (return to) STORE NO. 146-1000-1145
 ADDRESS 66 North Duane Pl
 CITY/STATE Sullivan, Mo ZIP 63880
 CREDIT MEMO ☐ REPLACE ☐ REPAIR ☒
 IN WARRANTY ☐ OUT OF WARRANTY ☐

MODEL/STYLE 700 B...
 DESCRIPTION 700 B...
 SERIAL NO./COLOR 11-28-80 DATE PURCHASED 11-28-80
 NATURE OF DEFECT: 11-28-80
 CUSTOMER'S NAME Matt S. Smith
 ADDRESS Sullivan, Mo
 CITY/STATE Sullivan, Mo ZIP 63880

S. V. B6228765
 SPOUSE TO THE
 DELOIT:
 5
 R. S.
 63080

WAL-MART STORES, INC.

CUSTOMER COPY

number 11 110007168. The life insurance
 forwarded to me from Central Sun
 1100, 134 E. Wall St. St. Louis Kansas
 67201. I contacted the customer and
 advised him he wanted a new
 bigger supply installed. He said
 he would like to have a new
 one in. When he showed
 me the one that was so
 small, I said.
 That one is not big in the
 matter.

Matt S. Smith
 11-28-80

FROM: CENTRAL GUN SHOP
124 E. WALL ST.
FORT SCOTT, KS. 66701

ATTENTION: REMINGTON-UMC CO.
ARMS SERVICE DIVISION
MILTON, N.Y. 15557

AFTER PAINTING, PLEASE RETURN THIS TO S.N. B6224768

ANY BILLING, OR FURTHER CORRESPONDENCE TO THE
CUSTOMER AT THE ADDRESS LISTED BELOW:

Wal-Mart 65
666 Service Rd
Selkirk Mo 63080
(Sling is in box)

Serial # B6224768. The rifle was
forwarded to you from Central Gun
Shop, 124 E. Wall St., Ft. Scott Kansas
66701. I contacted the customer and
asked him if he wanted a new
trigger assembly installed. He said
he would prefer to have a new
one put in. Please do this and
send the gun back to me as
soon as possible.

Thank you in advance for your help in this
matter.

Sincerely,
Ray H. Jones
Wal-Mart #65

THANK YOU
1-21-81

WAL-MART

Wal-Mart #65
66 South Service Rd
Sullivan, Mo 63080

Jan 29, 1981

Remington Arms Company Inc.
Shore, New York 13357

Gentlemen,

I received your letter concerning
test-firing and proof-testing of a
Remington 700 BTH Trn Mag Rifle
serial # B6229768. The rifle was
forwarded to me from Central Gun
Shop, 124 E. Wall St., St. Scott Kansas
66701. I contacted the customer and
asked him if he wanted a new
trigger assembly installed. He said
he would prefer to have a new
one put in. Please do this and
send the sum back to me as
soon as possible.

Thank you for your help in this
matter.

Sincerely,
Ray J. Adams
Wal-Mart #65

THOMAS
1-2-81

no more info

hold rifle for reply.

cc: Wal-Mart #00
bcc: E.F. Barrett
E.G. Larson
R.B. Sperling
J.E. Preiser
J.H. Chisnall
D.J. Sanita
R-33285

January 23, 1981

Central Gun Shop
124 E. Wall St.
Ft. Scott, Kansas 66701

Gentlemen:

Examination has been completed on the Model 700 BDL 7mm Rem. Mag. caliber rifle, serial number 86229768, which you returned to us when it allegedly fired as the safety was moved to the "fire" position.

The returned firearm which was produced in June of 1980, has been examined by our firearms experts who report that it contained our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all our necessary tests prior to shipment.

The general condition of the gun appeared to be good, however, it was noted there was a bright mark on the left side of the trigger guard. In going over the individual parts, we found the headspace normal, recoil shoulders normal, and chamber normal.

Examination of the rifle and trigger assembly could not duplicate the incident that was reported. All parts tolerances and dimensions were found to be normal, including sear-connector engagement, also; factory seals were intact on the trigger adjusting screws, indicating no alterations were made on the trigger outside our company. Trigger pull was within our specifications at 5 pounds.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the incident. When the safety is in the "on safe" position, the sear is lifted off of the trigger connector. At this time, very little effort is required to pull the trigger rearward, allowing the connector to be moved away from under the sear and, in this condition, on moving the safety to the "fire" position, the rifle will fire if the trigger is touched or otherwise contacted.

W. Paul Wolf

January 23, 1981

-2-

We trust that we have clarified the circumstances that could possibly have caused the accidental firing and, as a gesture of good will, even though there is nothing wrong with the present trigger assembly, we can replace it with another assembly at no-charge, to insure that the owners faith in the rifle is restored, or, the rifle can be returned as received. We will await the decision and reply.

Thank you for having afforded us this opportunity to examine the rifle and to be of service.

Sincerely,

J.A. Sekl, Supervisor
Firearms Product Service

JAS:tpg