

P.I. NO GUN EXAMINATION REPORT NUMBER: 657MODEL: 700 BDLGENERAL CONDITION: GOODR #: 09411OUTSIDE WORK: SCOPE MOUNTS ADDEDDATE: 3-5-82FIRED AMMO TYPE: NOT KNOWNFROM: KAYTON CO
3400 5TH ST HWY
READING PENN

& CONDITION:

GUN #: A6854273PROOF: REP INSP.: 86 TEST: 53CODE: BA-1-80HEADING: OKGA./CAL.: 270BREECH OPENING: OKCHECKED BY: MI HARDYRECOIL SHOULDERS: OKAPPROVED: SM 3/23/82CHAMBER: OKAPPROVED: APL 3/23/82

TEST:

APPROVED: PN 3/23/82

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: 3/23/82VERY GOOD, BOLT PLUG MISSING BY
SAFE BUTTONCOMPLAINT: GUN FIRED WHEN SAFETY WAS MOVED

INCIDENT:

COMMENTS:

Unable to duplicate customer complaint-OK on tick test- .015 Seal Engagement- .010 Seal left full size- Trigger Fails 3rd

510 RECEIVING and ESTIMATE REPORT ORDER R09411
3-5-82 3-10-82 APR 26 1982
RECEIVED ESTIMATED VER C/P CHARGE

FROM Hayton Co. (80397)
3400 5th St. Haverhill, Pa. 19605

MODEL and GRADE 700 BDL SERIAL NO. A6854222 DATE BA
Left Hand GRADE CODE 1-80

FOR COMPUTER REPR. ONLY
w/ Supp. mt. REPAIR CHG.
P.R.
PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Messed) (Ghosts) TOTAL

CUSTOMER'S COMPLAINT Gun fired when safety was moved

MAIN FAULT Find no fault w/ Trigger housing
assm

GALLERY REPORT DISMANT CODE

26655- Tr - Trigger - housing assm
Work done
D. Kack
Repairman

APR 28 1982

D. Kack

1141 MR DORN

Dennis:

Please hold
for

Kayton
3400
Reading

Gentle

Examination of the returned Model 700 BDL 270 Win. caliber rifle, number A6854273, which you returned to us because it allegedly "fired when the safety was moved".

The returned firearm, which was produced in January of 1980, has been examined by our firearms experts who report that it contained our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all our necessary tests prior to shipment.

The general condition of the gun appeared to be good, and it was noted that scope mount bases had been added after it originally left our factory. In going over the individual parts, we found the headspace, recoil shoulders, and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the incident that was reported. All parts tolerances and dimensions were found to be normal, including sear-connector engagement. Also, factory seals were intact on the trigger adjusting screws, indicating no alterations were made on the trigger outside our company. Trigger pull was within our specifications at five (5) pounds.

Based on our findings, Remington Arms Company, Inc cannot accept any responsibility for the incident. It is possible that while the safety lever was being moved from the "safe" to the "fire" position, the trigger was inadvertently contacted. When the safety lever reached the "fire" position, the gun then discharged - as it is designed to do - because the trigger was being pulled with the gun no longer on "safe".

Bill Rack

1-
Replace Trigger Gun
Assembly
for Mr DORN
Phone 5/21/81

C.O.D. TAG
SHIPPER INSTRUCTIONS
FULL TAG (OUTLINE)
COMPLETELY ENTERED
C.O.D. AMOUNT IN
BOTH BOXES WORDS
"CASH ONLY" MUST
BE ENTERED ON IN-
STRUCTION LINE AND
CHECKED ON CON-
SIGNEE RECEIPT
DRIVER IS NOT AU-
THORIZED TO AC-
CEPT CHECK
REMOVE BARRING
AND PLACE ENTRY
FORM ON FRAGILE
LABEL

DRIVER INSTRUCTIONS
WORKS "CHECK" AND
SIGNATURE MUST BE
ENTERED ON IN-
STRUCTION LINE
UPON ACCEPTANCE
OF CUSTOMER
CHECK

United Parcel Service
81104 5-75 (COMM 177)

KAYTON CO.
3400 Fifth Street Highway
READING, PENNSYLVANIA 19605

REMINGTON
ARMS SERVICE DIV
ELIOM NY 13357

CONSIGNEE RECEIPT

C.O.D. AMOUNT

DOLLARS	CENTS
4	00

☐ CHECK HERE
IF CASH ONLY
SEE INSTRUCTIONS

SHIPPER NO

DATE RECEIVED

RECEIVED BY

Annis,
Please hold this rifle
for reply.
Thank you,
Jim

cc: P.T. Millener
K.D. Green
R.B. Sperling
D.J. Sanita
R#09411

March 23, 1982

Kayton Company
3400 Fifth Street Highway
Reading, Pennsylvania 19605

Gentlemen:

Examination has been completed on the Model 700 BDL 270 Win. caliber rifle, serial number A6854273, which you returned to us because it allegedly "fired when the safety was moved".

The returned firearm, which was produced in January of 1980, has been examined by our firearms experts who report that it contained our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all our necessary tests prior to shipment.

The general condition of the gun appeared to be good, and it was noted that scope mount bases had been added after it originally left our factory. In going over the individual parts, we found the headspace, recoil shoulders, and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the incident that was reported. All parts tolerances and dimensions were found to be normal, including sear-connector engagement. Also, factory seals were intact on the trigger adjusting screws, indicating no alterations were made on the trigger outside our company. Trigger pull was within our specifications at five (5) pounds.

Based on our findings, Remington Arms Company, Inc cannot accept any responsibility for the incident. It is possible that while the safety lever was being moved from the "safe" to the "fire" position, the trigger was inadvertently contacted. When the safety lever reached the "fire" position, the gun then discharged - as it is designed to do - because the trigger was being pulled with the gun no longer on "safe".

-1-

phone 4/21/82
Rep / ACE TRIGGER
ASSEM
MR DORN

Bull Rack

March 25, 1982

-2-

We trust that we have clarified the circumstances that could possibly have caused the accidental firing and, as a gesture of good-will, even though there is nothing wrong with the present trigger assembly, we can replace it with another assembly at no-charge, to insure that our customer's faith in the rifle is restored, or, the rifle can be returned as received. We will await the decision and reply.

Thank you for having afforded us this opportunity to examine the rifle and to be of service.

Sincerely,

J.A. Stekl, Supervisor
Firearms Product Service

JAS:tp

R

KAYTON COMPANY
3400 5th ST. NW
READING, PENNA. 19601

No. 80397

TO BE
FILL
IN

TO REMINGTON SERVICE

DATE 2/24/82
INVOICE DATE INVOICE NUMBER

MERCHANDISE CLAIM

ILLINOIS NY 13357

M 94560

GENTLEMEN: WE MAKE CLAIM UPON YOU FOR THE FOLLOWING:

STOCK NO.	QUAN.	ITEM	PRICE	AMOUNT
700	1	# A6854273		
		1) Remington-Union Safety		
		2) Customer Claims Gun Fired		
		when Safety moved		

DATE SHIPPED PACKED BY SHIPPED BY Total Amount of Claim →

Remarks See Service

Date Approved By Signed

FOR THE U.S. ARMY & U.S. MARINE CORPS AND U.S. AIR FORCE, THE U.S. NAVY, U.S. COAST GUARD, U.S. AIR FORCE, U.S. NAVY, U.S. COAST GUARD, U.S. AIR FORCE

TOTAL REPAIR CHARGE 75.00
TAX 7.51 INSURANCE 6.00
PARCEL POST UPS 2.25
TOTAL CHARGES 83.25

☐ THE ITEM ABOVE HAS BEEN RECEIVED AND IS BEING REPAIRED
SHIPPING WILL BE MADE APPROXIMATELY
☒ THIS CLAIM IS MADE TO THE U.S. ARMY FOR THE ITEM. IF THE ITEM IS NOT SATISFACTORY PLEASE APPROVE BY SIGNING BELOW. RETURN FIRST
TO REMINGTON ARMS CO. INC. IN NEW YORK. RETURN SECOND TO REMINGTON ARMS CO. INC. IN NEW YORK. RETURN THIRD TO REMINGTON ARMS CO. INC. IN NEW YORK. RETURN FOURTH TO REMINGTON ARMS CO. INC. IN NEW YORK.
CUSTOMERS SIGNATURE TWO WEEKS

APR 28 1982

Remington

