

P.I. NO GUN EXAMINATION REPORT NUMBER: 538 MODEL: 700 BDL
 GENERAL CONDITION: FAIR R #: 26528
 OUTSIDE WORK: SCOPE SCREWS REMOVED DATE: 10-22-81
 FROM: CHARLIE'S
SPT. GOODS
7401 H-MANUAL 2-70
N.E. ALBUQUERQUE, N.M.
 FIRE ARMS TYPE: NOT KNOWN GUN #: A6634154
 & CONDITION: _____ CODE: 0Q-7-78
 PROOF: R INSP.: 9 TEST: 111 GA./CAL.: 270
 READING: OK CHECKED BY: M-HARDY
 BREACH OPENING: OK APPROVED: APR 11/19/81
 RECOIL SHOULDERS: OK APPROVED: RS.M. 11/19/81
 CHAMBER: _____ APPROVED: RA 11/19/81
 TEST: _____ APPROVED: WJB 11-19-81
 APPROVED: DA 11/19/81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: SL 11/19/81
S LIGHT SCRATCHES ON RIGHT SIDE OF STOCK

COMPLAINT: FIRING WHEN SAFETY WAS REMOVED

INCIDENT: _____

COMMENTS: Unable to duplicate customer complaint.
4 1/2# Trigger Pull, Passes trick test, .009 Sec. Lift

Replace fire control - no charge. APR

RECEIVING and ESTIMATE REPORT

ORDER R 26528

1215
10-22-81 ESTIMATED 11-30-81 VIA TRUCK CHARGES

FROM Charlie's Spt. Goods

DEC 01 1981

7401 H. McNaught Blvd NE Albuquerque, N.M.

nd GRADE 700 AAL 270 WIN SERIAL NO. A6634154 DATE CODE 09

GRADE
CODE

7-78

PUTTER REFER. ONLY

61 Sling, Swiss.

REPAIR CHG.

55

INS.

PARCEL POST

CONDITION: (New) (Slightly worn) (Very worn) (Misused) (Quoted)

TOTAL

OWNER'S COMPLAINT

discharged when safe was removed

AULT

GALLERY REPORT

DEMENT
CODE

26345 trigger assembly

parker chamber

this work done

Clean, Tight, Target

Repairman

DEC 10 1981

Charlie's

SPORTING GOODS, INC.

7401-H Menaul Blvd., N.E. — 505/884-4545
Albuquerque, New Mexico 87110
Hunting & Fishing Specialists

**MEMO
LETTER**

TO: Remington Service Center
6134 Dornum Ave.
Bridgeport Conn 06602

DATE Sept. 14, 1981
SUBJECT Repair.

1 ea. Rem. Mod. 700 RBL
S.N. A6634154

Customer claims gun discharges
when safety was removed, please
repair as needed.

Thank you.
C. Domenici.

N. Raymond
16535

4 1/2 H Trigger Pull, passes truck test, .009 lead lift

Replace fire control - no charge. 4/11