BARBER - Kinzer PPS GAL RE0000376

Remington.

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

Mr. Earl Batchelor 1228 Adobe St. Great Falls, Mt 59404 January 9, 1987

Dear Mr. Batchelor:

Your letter of December 15, 1986 that was addressed to our Firearms Product Manager, Bridgeport, Ct., regarding the safety operation of your Model 700 Classic 300 H & H Mag caliber rifle, serial number B6463236, has been forwarded to this office for response.

All Model 700 rifles produced after 1981 do not have the "bolt lock" feature, i.e.- the bolts can be raised with the safety in the "on-safe" position. Older Model 700 rifles do lock the bolt with the safety on.

The bolt-lock was eliminated based on the results of an independent marketing survey in which a greater percentage of the shooters felt it was not a necessary feature and preferred the capability of opening the bolt with the safety on.

If you do desire the bolt-lock feature on your rifle, we can install the necessary parts at a charge of \$15.00 to cover parts, installation and testing. If you are interested, please send your rifle via insured UPS to:

> Remington Arms Company, Inc. 14 Hoefler Avenue Ilion, N. Y. 13357 Attn: J. A. Stekl, Supervisor Product Service

In addition, please print "STEKL" on both butt ends of the shipping box in bold letters.

Thank you for your interest in Remington products and for affording us this opportunity to be of service to you.

Sincerely,

10 A. Stekl, Supervisor

Froduct Service

JAS:cm

all a line and a line and a second statement of the second statement of the

.....