

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 002023
 OUTSIDE WORK: No DATE: 1-27-72
 FROM: BAY CITY HDW. CO.
 FIRED AMMO TYPE: - BAY CITY, MICH.
 & CONDITION: _____ GUN #: 6500965
 PROOF: R.E.P.-M INSP.: - TEST: 13 CODE: NONE
 HEADING: O.K. GA./CAL.: 243 WIN.
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

MINUS STOCK. TRIGGER PULL 4 1/2 LBS. - O.K. ENGAGEMENT
.008 (.020 MIN.) NEW RIVETED HOUSING CONNECTOR
1.093 M/D = 1.080 TRIGGER 1.076 M/D = 1.076
1.083 TRIGGER 1.079 M/D = 1.079. BURRS ON
CONNECTOR SIDES.

COMPLAINT: "FIRES ON SAFE"

INCIDENT: MAY HAVE FOLLOWED DOWN WHEN SAFE WAS
RELEASED.

COMMENTS: ENGAGEMENT IS SET TOO CLOSE, WITH THE
BURRS ON THE CONNECTOR AND CLOSE ENGAGEMENT,
IT IS POSSIBLE THAT THE CONNECTOR FAILED TO
RETRACT WHILE THE SAFETY WAS ON THEN FOLLOW
DOWN OCCURRED WHEN THE SAFETY WAS RELEASED.