

BARBER - Kinzer PPS GAL RE0000391

CEIVING AND ESTIMATING REPORT

ORDER NO.

RECEIVED 12/22/93	DATE OPENED 12/02/93	DATE CODE PV 6-79	SERIAL NUMBER A6786035	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	SDL
----------------------	-------------------------	----------------------	---------------------------	-------------------	------------------------------	-----

Product Service ✓ R 2-93 25851

Lead Supply

BAYVILLE SPTG GOODS INC
259 BAYVILLE AVE
BAYVILLE

NY 11709

SHIP TO:

BAYVILLE SPTG GOODS INC
259 BAYVILLE AVE
BAYVILLE

NY 11709

CUST NO: 011859 C.O.D.

INT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 12/16/93	VIA 5640479750
CONDITION					REPAIR CHARGE 25.00
NEW					EXCISE
SLIGHTLY WORN					TAX
ORN					INSURANCE
VERY WORN					UPS
UNREPAIRABLE					PARCEL POST
VARIED					TOTAL

COMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E						
BER GROUP						
ASSY.						
REL ASSY.						
ASSY.						
D						
L						
FAULT						

"When rifle is moved to the firing position, the firing pin intermittently makes contact"

Upon receipt, unable to duplicate customer concern. However examination reveals that the bolt stop release and rear safety can be being shipped from the factory and trigger assembly being bound with sticky waxy substance. Rifle mfg 1979

COMMENTS

Replace trigger assembly & clean action at 1/2 normal cost, as gesture of good will

REPAIRMAN JTB	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1-82