

SPORTSMAN-58 BARREL EXTENSION

At the May meeting, the upset of the Locking Notch in some guns after a comparatively few rounds of shooting had been noted. A check of endurance guns indicates that while there is upsetting that there is no apparent problem. The same condition exists in Model 870 guns.

As a further check, samples of Barrels with indications of upsetting are being furnished Arms Design and Chem. & Met. for checking.

83

VGD:EK
6/4/56

WIL00113