

RECEIVED
FEB 27 1987

E.F. C. 111-102

HERBERT J. BEIL, M.D.
658 WEST MARKET STREET
LIMA, OHIO 45801
PHONE 229-0816

February 24, 1987

Mr. Edward Sienkewicz
Remington Arms Company, Inc.
Product Service
Ilion, New York 13357

Dear Mr. Sienkewicz,

As we discussed the other day on the telephone, I own a Remington Model 700 LH 7 mm Magnum (No. 36532467). This was purchased 9/27/84. The initial problem with the weapon was an unreliable extractor. The weapon was sent in and this taken care of adequately.

However, I have remained unhappy with the weapon, in that the bolt will not remain in the down and locked position when the safety is on. I used the gun to hunt in rugged country and carried the gun with a sling on my back. On several occasions, the bolt handle would open up and the round would fall out of the chamber and be lost. I had to improvise to avoid this by putting a rubberband around the trigger guard onto the bolt handle. This works well in warmer weather, but in sub-freezing is quite inadequate.

As we discussed, a modification is now possible to remedy this and restore the action to a bolt lockdown and secure position when the safety is on. I would kindly request that this bolt be modified accordingly and will be sending the rifle back shortly by UPS.

Thank you for your kind attention.

Sincerely,


Herbert J. Beil, M.D.

SHIP GUN AFTER APRIL 155

rk