

Model 550 Testing - 8,000 rds.

		Ejection	Locking Up	Blow Back	Stem Chamber	Bolt Override	Light Indent	Double Fire	Feed From Mag.	Rate
0- 50	Rem. S. HS.	11		2	2		2		1	3.6%
51-100	" S. HS. (HP)	11			3				4	4.
101-150	Peters S. HV(HP)	9			4					3.4
151-200	Win. S. SS(HP)	3							2	1.2
201-250	West. S. SX	10								2.8
251-300	Rem. S. HS	23			1				12	17.8
301-350	" L. HS									3.4
351-400	Peters L. HV	2*					1		3	6.0
401-450	Fed. L. HS						1			4.2
451-500	Win. L. SS									2.8
501-550	West. L. SX									6.2
551-600	Rem. LR HS	7								5.2
601-650	" LR HS(HP)	3								9.4
651-700	" LR Std. V	6								6.8
701-750	Win. LR SS(HP)	12					2			5.8
751-800	Peters LR HV(HP)	12			1		9			10.6
801-850	Fed. LR HS	18								7.6
Total		127	192	137	11	0	15	0	22	6.3%
		14.9%	22.5%	16%	1.2%	0	1.7%	0	2.5%	

*One of these malfunctions failed to extract.

S. M. ALVIS

-3-

February 4, 1957

W1100269