

cc: D.E. Miller
R.A. Williamson
H.J. Hackman
V.G. DeReus
W.A. Best
W.E. Leek
H.L. Hameister

Alton, New York
March 4, 1957

S. M. ALVIS

SPORTSMAN-58 - 12 GA. - 40 FT TEST

For your information, ten (10) of the subject guns were withdrawn from Warehouse 2-28-57 and subjected to test on this same date. Each gun was fired 300 rds. using twelve (12) types of ammunition. Five (5) shooters were used, and five (5) stations on the skeet field as firing points. The results are as follows:

Gun No.	Mal.	Rate	Type
96843	1	.33%	1 Shot chamber (right)
86593	2	.66%	2 Shot chamber (right)
96821	3	1.0%	2 Shot chambers (right) 1 Shot chamber failed to rise (Binding on action bar)
86490	1	.33%	1 Shot under extractor
86737	1	.33%	1 Shot chamber (right)
86544	1	.33%	1 Shot chamber (right)
96911	None	-	The operating handle fell out once.
97240	2	.66%	2 Shot chamber (right)
96841	1	.33%	1 Failures to feed from mag.
86747	1	.33%	1 Failure to trip latch.

Overall rate for 13 Mal: actions is .43%.

CONCLUSIONS

The performance of this gun at the present lot is excellent and shows an improvement.

CJT:T

J. Theriault
J. Theriault
Supervisor - Testing Unit