

P.I. YES SERIAL NUMBER: 52 MODEL: 700 BDL
 INTERNAL CONDITION: METAL WORN BRIGHT R #: 30015
 OUTSIDE WORK: STOCK REMOVED + DATE: 12/15/78
SCOPE SCREWS FROM: RAYMOND
BENJAMIN
710 W. 3 RD
MCCOOK NE8.
 FIRED AMMO TYPE: UNKNOWN GUN #: 63645-78
 & CONDITION: _____ CODE: W-T-8-70
 PROCP: A INSP.: 63 TEST: 49 GA./CAL.: 270
 HEADING: OK CHECKED BY: M-HARDY
 BREACH OPENING: OK APPROVED: 9/28/79
 RECOIL SHOULDERS: OK APPROVED: 10/2/79
 CHAMBER: OK APPROVED: 12/2/79
 TEST: _____ APPROVED: 12/2/79
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 12/2/79
METAL BRIGHT AT MUZZLE
JEWELING ON BOLT WORN OFF
COLOR OFF FRONT SIGHT STOCK, FLOOR
PLATE, MAG-BOX SPRING & FOLLOWER MISSING
 COMPLAINT: FIRE UPON TAKING OFF SAFETY
 INCIDENT: SHOT A HOLE IN FLOOR OF SCOUT.
 COMMENTS: Unable to duplicate incident. Excessive
oil in fire control could cause impaired mechanism
function.

