

MODEL 878 AUTOMASTER

12 Gauge Magnum

This item remains in deferred status.

POWDER ACTUATED TOOLS

STUD DRIVERS

MODEL 455A FIRE CONTROL

The Research & Development reports that functioning difficulties have been encountered with the redesigned sear block of the Model 455 Fire Control, when used with the Heavy Duty 3/8" tool only. With all other tools, results are satisfactory.

The Research & Development Department has 10 Heavy Duty 3/8" tools in firing tests to determine cause of functioning difficulties.

The Plant is concerned over the effect delays may have on accomplishing forecast quantities of the 3/8" Heavy Duty tool. The Research & Development Department will determine means of correcting the problem, and will notify the Plant as soon as correction is accomplished.

The Sales Department reported reference of complaints regarding loose head space screws on Model 455A tools to the Plant on June 2, 1959; and reference of further complaints to the Plant on July 1, 1959, regarding interference fits between gas seal barrel shoulders and guide tubes of the Model 455A.

The Plant states that these complaints are being investigated, but analysis is not yet complete.

INDUSTRIAL TOOLS

STUNNERS

MODEL 412 ONE-HAND STUNNER

Assembly of Model 412 One-hand Stunners was started on Schedule during the middle of May, 1959.