

7/21/92

to: Arms Service
From: Product Service

SUBJECT: R# 91-27077; M/700 270Win; S.N. 6522281
DENNIS BERNHARDT

The customer has accepted offer to replace trigger assembly in subject rifle at no-charge.

- 1.) Install a new no bolt lock safety trigger assembly in rifle
- 2.) Thoroughly clean all rusted areas of rifle and properly lubricate
- 3.) Return rifle to owner — do not charge handling or return shipping.

Thank you,

JLB