

710 Cust. Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 025800
OUTSIDE WORK: NO DATE: 12-14-72
FROM: BILL'S SPT. # HOBBY ^{SHOP}
FIRED AMMO TYPE: - ONEDNTA, N.Y.
& CONDITION: _____ GUN #: 6365666
PROOF: R.F.P.-C ^{ASSEMBLER 41} INSP.: 88 TEST: 29 CODE: WT = 8/70
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .015 (MIN. 15.020)
CONNECTOR CLEARANCE ON TRIGGER = 1.073 (MODEL DRAWING = 1.079) ^{1.076}
BURRS ON TOP SIDES OF TRIGGER.

COMPLAINT: GUN FIRED WHEN SAFETY WAS PUSHED OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE TRIGGER BIND COULD CAUSE FAILURE TO
RETRACT AND FOLLOW DOWN, THE UNDER MIN. ENGAG-
EMENT CONTRIBUTING TO THE MALFUNCTION.