

P.I. 50 GUN EXAMINATION REPORT NUMBER: 219 MODEL: 700-002
 GENERAL CONDITION: FAIR R #: 10000
 OUTSIDE WORK: REAR SIGHT REMOVED DATE: 3-26-80
SCOPE BASE ADDED FROM: 2654E B122103
 FIRED AMMO TYPE: NOT KNOWN MESA 2P2
 & CONDITION: _____ GUN #: 6524577
 PROOF: (REP) M INSP.: 9 TEST: 97 CODE: 211-2-72
 HEADING: OK GA./CAL.: 2506
 BREACH OPENING: OK CHECKED BY: JA-42004
 RECOIL SHOULDERS: OK APPROVED: JAH 4/23/80
 CHAMBER: OK APPROVED: PG 4/23/80
 TEST: _____ APPROVED: WDS 4/23/80
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: Q/B 4-23-8

SLIGHT MARKS ON BRASS

BRIGHT METAL MARKS ON BRASS

COMPLAINT: FIRE WHEN SAFETY WAS MOVED TO OFF

INCIDENT: _____

COMMENTS: Sear lift .0095", Trigger Pull 4", Passed
Trick Test.

Fire control adjusting screws possibly adjusted
outside of Remington and resealed with red sealant.

Unable to duplicate customer complaint.