

RECEIVING AND ESTIMATING REPORT

INITIAL JJH		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/12/90	DATE OPENED 12/18/90	DATE CODE DE 9-84	SERIAL NUMBER B6633212	MODEL AND GRADE 700 30-06 ADL		ORDER R 90-3298	
ACCESSORIES W/STUDS							

FROM:	SHIP TO:
BIRLEW, CHARLES 2117 S KIMBROUGH SPRINGFIELD MO 65807	BIRLEW, CHARLES 2117 S KIMBROUGH SPRINGFIELD MO 65807

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 1-7	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *fires on bolt closing, bolt clears sticks.*

MAIN FAULT *Disassembled, firing pin with ar motion as follow-down as bolt is close. Disassembly of rifle revealed that trigger assembly and bolt stop are contaminated with gummy substance. Internal trigger parts are not moving freely & the rear sear assembly is sticking to the trigger housing side - plate. Insufficient maintenance of rifle.*

PARTS *Send quotation to clean present trigger assembly (if possible) or offer to replace trigger assembly with new one at 1/2 normal cost, as a gesture of good-will.*

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/9