

Gun	Total Endurance Rds. Shot	Fail to Eject	Malfunction Break Down				Fail to Feed	Other Box Related Events		
			Stem Low	Stem High	Bolt Over-ride			Straighten Box	Box Btm. Detaches	Doesn't Latch
B-11	10,000	4	83		1		1	3	1	3
B-12	5,000	14	1					4		
B-13	5,000	7	6		2			3	5	2
B-14	1,000	1			1			3		
B-15	2,000	6						3		
B-16	2,000	12	4					13		
B-17	2,000	3	1	1				12		
B-18	1,000		4					11	1	
B-19	1,000	20						11	1	
B-20	1,000	2	1					12		
	30,000	69	100	1	4		0	75	8	5

Broken Parts:

1. Gun B-14: Bolt handle broke off at braze during inspection.
2. Gun B-12: Firing Pin broke at 1,496 rds. in thread area (replaced with pin from B-14 (1,320 rds)).
3. Gun B-12: One ear on Bolt Plug broken off. Noticed at 3,000 rd. inspection.

General Comments:

1. Gun B-11,B-12,B-13: Bolt Stop would not work 100 % of the time at approx. 3,000 rds.. Shimmed Stock to fix.
2. Gun B-13: Number of FTE's may be low. Chronic FTE malfunctions noted at 4,400 rds..

83

ET07149

Confidential - ~~BARBER~~ - 5.22.06r0001318 Order

Williams v. Remington