

*Tracy  
Jim STEEL*

T.H. Blakeney  
Rt. #1 Box 352  
Clinton, Arkansas  
8 October 1985

Firearms Product Manager  
Remington Arms Company, Inc  
939 Barnum Ave  
P.O. Box 1939  
Bridgeport, Connecticut 06601

Dear Sir:

On 7 June 1985 I purchased a 7mmBR Pistol Serial #B7518994.  
It took me a couple of months to get it scoped and bullet moulds ordered etc.  
For the first few rounds fired it done OK, however with continued firing  
the forearm pulls away from the BARREL Approximately  $\frac{1}{4}$ " and the groups fired  
are about twice as high as they are wide. Having never owner a nylon stock  
before is this pulling away from the barrel normal? Don't look too good but  
~~XX~~ I taped the stock and barrel together with nylon tape and that seems to  
help a bit. Please advise if this is normal??

Thanks:

*T.H. Blakeney*  
T.H. Blakeney

RECEIVED  
OCT 22 1985  
CONSUMER SERVICE

RECEIVED

OCT 28 1985

J. A. STEEL