

RECEIVING AND ESTIMATING REPORT

INITIAL **FPS** CUSTOMER ORDER NO. ORDER
R 94-13571

DATE RECEIVED **04/19/94** DATE OPENED **04/20/94** DATE CODE **PH 6-87** SERIAL NUMBER **B6867477** NEW SERIAL NUMBER MODEL AND GRADE **700 270 WIN ADL**

ACCESSORIES **W/STUDS** SCOPE BASE **LASIGHTS**

FROM: **BLOOM, ROBERT
R 6 BOX 169
LITTLE FALLS MN 56345** SHIP TO: **BLOOM, ROBERT
R 6 BOX 169
LITTLE FALLS MN 56345**

CUST NO: **096230 CLO.D**

ACCOUNT NUMBER ACCOUNT NUMBER NC PROM. DATE ESTIMATED VIA **UPS**

GUN CONDITION
☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE **20.00**
 EXCISE
 TAX
 INSURANCE
 UPS
 PARCEL POST
 TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5			E4	F4
WOOD				D3	E5	F5
METAL			C2			

MAIN FAULT *Good 3mm hand moved, unable to close bolt upon reset. Trigger assembly jammed up from wrong adjustment and poor maintenance. Action also not good during trigger pull 44.00. That assembly appears to have been modified. See test over.*

COMMENTS *Up the barrel to trigger assembly and then adjust it to normal adjustment. Not in good condition.*

REPAIRMAN **TAL** PROOF CLEAN TEST TARGET PATTERN

GALLERY TESTER DATE DATE DATE DATE DATE DATE

OFFICE COPY RD6925 REV. 1/94