

EXHIBIT 1

REMINGTON ARMS COMPANY, INC.  
Ilion, New York

September 17, 1969

CC: G. M. Calhoun - Bdpt.  
J. E. Dickey - "  
F. E. Morgan - "  
C. C. Clair - "  
R. A. Williamson  
S. M. Alvis  
V. G. DeReus  
L. J. Boyle  
A. D. Kerr

E. G. LARSON  
BRIDGEPORT

MODEL 1100 - FIELD SERVICE REPORTS - 1968-1969

We have completed an analysis of R. L. St. John's firearms service report on the World's Skeet Championship and the Grand American Handicap held last month. In addition, we reviewed St. John's reports for these same events in 1968. With some exceptions, field experience correlates with the audit and gallery tests performed at the plant and with the extended endurance tests being conducted by R & D. We have listed each of the items reported by St. John and the current status:

ITEM: BURR IN MAGAZINE TUBE

Cause: Steel headed shells of the magazine follower strike the barrel support at the end of the magazine tube and raise a small burr causing a failure of the shell to feed from the magazine tube.

Corrective Action: The present chamfer on the barrel support will be increased to reduce the likelihood of a burr. In addition, R & D is testing a plastic magazine follower which will not mar the barrel support.

EXHIBIT 1