

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 04/05/93
 ENTER REPAIR NUMBER -----> 9223376 09 17 32
 SERIAL NO: B6277549 NEW SERIAL NO: MODEL: 700
 FROM: (CUST NUM: 008349) BOBSARMYNA GA/CAL: 7MM MAG
 BOBS ARMY & NAVY TYPE: ADL
 C/O NBS ACCESSORIES: W/STUDS
 229 E MARKET ST
 CLEARFIELD PA 16830
 SHIPPED TO:

DATE CODES: BB 1-81
 OTHER ACCESSORIES:
 L/REAR SIGHT

COMMENTS:

DATES:		TO	FROM	
RECEIVED	10 29 92	GALLERY	00 00 00	00 00 00 ENTERED BY: FPS
OPENED	11 04 92	PROD SERV	11 17 92	11 18 92 REPAIRMAN: HB
ESTIMATED	11 19 92	TAG GUNS	00 00	TYPIST:
PROMISED	00 00 00	REJECTED	00 00	CORRESPONDENT:
REPAIRED	00 00 00	CASH RECEIVED:\$	0.00	BILL TYPE: W
SHIPPED	01 29 93			

BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9223376 REPR NOT AUTHORIZED WILM INVOICE PR 04/05/93
 CUSTOMER NAME: BOBS ARMY & NAVY 09 17 45

REQUEST: "GUN DISCHARGES ON OCCASION WHEN COCKING WEAPON"
 MAIN FAULT: NO FAULT FOUND - CANNOT DUPLICATE ABOVE COMPLAINT & CANNOT
 MAKE RIFLE MALFUNCTION IN ANY WAY. RIFLE OPERATES PROPERLY
 IN ALL RESPECTS.
 TRIGGER PUL 5 POUNDS; SEAR-LIFT .007"
 DATE OF MFG: 01-81

PARTS:	\$	0.00	1	26345	TRIGGER ASSEM RH
	\$	0.00		19900005	TEST
LABOR:	\$	0.00	1.		RETURN RIFLE AS-IS
	\$	0.00	2.		INSTALL NEW TRIG ASSEMBLY AT 1/2 NORMAL COST, AS A
	\$	0.00			GESTURE OF GOOD-WILL, IF THAT WILL BETTER RESTORE
	\$	0.00			CONFIDENCE IN THE RIFLE.
	\$	25.00			TRIGGER ASSEM - 1/2 PRICE
	\$	0.00			39-D/A 111-9450
	\$	0.00			HB/HAR
	\$	0.00	**		RETURNED AS RECEIVED - CUSTOMER'S PROPERTY

REPAIRMAN'S INITS: HB NUM OF WKS: 00 CORRESPONDENT'S INITS:
 TOTAL VALUE:\$ 0.00 PF1 = INQ PF2 = ESTIMATE
 NO MORE DATA AVAILABLE FOR THIS REPAIR

*Customer gave us go ahead early Jan 93 - per Jim
 at Bob's - We set as rec'd?
 a lot of work at this in northern B & S well*