

(E) XACT

10/02/71
09 59

9-30-91

Phone:

(504) 882-7392

Remington Arms Co, Inc
Arms Service Div.
Ilfon, New York, 13357

MODEL: 700
GA/CAL: 30-06
TYPE: BDL
ACCESSORIES: W/STUDS

TS: WU 8-71
IER ACCESSORIES:
YEAR SIGHT

Dear Sirs, Sen. # 6471674

I purchased the accompanying
model 700 BDL 30-06 in approx. 1972.

At the time and to date, the
only way to clear a round from
the chamber is to put the safety
on fire and then work the bolt.

I have never felt comfortable
with this procedure. Is this
normal? Please reply.

During our last hunting
season the weapon began
acting strangely and dangerously.
The problems are:

1. When attempting to move
the safety from safe to fire
and a round is in the chamber,
the weapon automatically fires.

ENTERED BY: LCS
REPAIRMAN:
TYPIST:
CORRESPONDENT:
PFS = PRINT RME

CAROL M.

THK IS

