

GENERAL - contd.

The Model 870 polyurethane foam Stock for police guns failed. Marketing was requested to provide samples of Stocks that are broken in police use.

BENCH REST BULLETS

R & D reported that production of bench rest bullets is still at the 100,000 per month level. However, a photo-electric sensor has been installed on the pointing press so that 100% attendance is no longer required. A magnetic coil sensor has been ordered for the blank and cup. Remington is negotiating with Russell on a new hopper for the first draw. The Black Rock cutoff machine has been modified and should be installed and in operation the week of September 18.

TRAPSELECTRIC TOURNAMENT TRAP  
(Introduction 1973)

Production reported that all remaining components for the Electric Tournament Trap are promised for delivery the week of October 2. Trial and pilot sub-assembly of the first trap has started.

R & D reported that these delays in deliveries on castings, especially the base, have moved testing of the first assembly back to at least October 15.

HANSEN TRAPS

R & D reported difficulties of adjustment and excessive dispersion of thrown targets are the main problems found in testing the Hansen trap.

83