

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-15174

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

07/16/92

07/28/92

EC 10-82

B6415937

700 30-06

BDL

ACCESSORIES

W/STUDS

FROM:

BOWLER, DWIGHT E
813 CHARLES
YPSILANTI

MI 48198

SHIP TO:

BOWLER, DWIGHT E
813 CHARLES
YPSILANTIMI
48198

CUST NO: 064175

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

IN CONDITION

NEW
LIGHTLY WORN
WORN
VERY WORN
UNREPAIRABLE
MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CLE

A1

B1

IGGER GROUP

B2

E1

F1

RT ASSY.

B3

E2

F2

REL ASSY.

B4

E3

F3

C ASSY.

B5

E4

F4

DOD

C1

D2

E5

F5

ETAL

C2

IN FAULT.

Cannot duplicate complaint. Rifle operates normally in every respect. The only thing that was noted is that trigger movement is somewhat slow - there is an excess of oil inside the assembly. trigger pull - 4 1/2 pounds; rear lock - .013"

ITS

COMMENTS

We can clean present trigger assembly and return, or, we can replace the trigger assembly at \$145.00 plus cost of good - with 1/2 that will be the stated confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 1/92