

TRAPS - contd.ELECTRIC TOURNAMENT TRAP - contd.

It apparently was due to lack of adequate oil level. A new gear box has been shipped and arrangements have been made for its installation. Good reports have been received from the other field locations.

Marketing reported that six traps are at field demonstration locations. Preliminary results look good. A performance report will be given at the March meeting.

HANSEN TRAPS

R & D reported that binding of the lifter mechanism on the Hansen skeet trap developed during use at the Ilion Fish and Game Club. Dirt and rust, along with lack of lubrication, aggravate this problem. This is a fault experienced on previous Hansen models.

R & D reported that with the current dollar devaluation, selling of the Hansen trap would be a money losing venture. It appears better in the long run to develop the Remington skeet trap.

Marketing recommended that Hansen should be advised to go no further on this program. Also costs and schedules for the Remington skeet trap should be developed.

It was indicated that not having a reliable, serviceable skeet trap does affect Remington total gun club business.

Committee Action:

The Operations Committee agreed to terminate work on the Hansen trap and settle any existing business arrangements equitably. Costs and schedules are to be developed for the proposed Remington skeet trap.