

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 EOL
 GENERAL CONDITION: NEW R #: 006000
 OUTSIDE WORK: SCORE MOUNTED DATE: 3-13-72
 FROM: BRACE, HON. CO.
 FIRED AMMO TYPE: _____ BRAUNENBURGER, PA.
 & CONDITION: _____ GUN #: 6243354
 PROOF: R.E.P. INSP.: 73 TEST: 87 CODE: 05-2/69
 HEADING: _____ GA./CAL.: 308
 BREECH OPENING: _____ CHECKED BY: C. PROST
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEALS INTACT, ENGAGEMENT .070 (MIL) (SEE P. 1)

CONNECTOR CLEARANCE ON TRIGGER = 1.069 ($\frac{1.079}{1.059}$) TRIGGER

CLEARANCE ON CONNECTOR = 1.090 ($\frac{1.093}{1.083}$) THIS ADDS UP TO
.014 MORE CLEARANCE BETWEEN CONNECTOR AND TRIGGER THAN
SPECIFICATIONS.

COMPLAINT: FIRES WHEN SAFETY IS RELEASED

INCIDENT: FOLLOW DOWN

COMMENTS: THE EXCESSIVE CLEARANCE BETWEEN THE TRIGGER
AND CONNECTOR ALLOWS THE CONNECTOR TO PICK UP
AND CATCH ON THE SEAR PREVENTING RETRACTION
CAUSING FOLLOW DOWN.