

though after it was installed by the St. Louis Gun Shop.
 though it was mounted on 5 1/2 barrels, no
 was ever left with safety in the "safe" position
 at 0125" ~~pm~~

Since the trigger assembly was found to be in
 perfect condition and with no signs of
 malfunctioning, the firearm was returned to
 the owner as requested. The owner stated that
 he would not be using the firearm until the
 next day and the trigger assembly.

It is quite possible that the shooter may have
 accidentally depressed the trigger while
 the safety was in the "safe" position. This method
 of manipulating the firearm was not in
 firing with the safety in the "safe" position.

Thank you for your interest in the firearm
 to ensure the safety of the owner.