

RECEIVING AND ESTIMATING REPORT				COMMENTS <i>To Product Service</i>		ORDER R 93-13398	
INITIAL FPS	CUSTOMER ORDER NO.						
DATE RECEIVED 06/09/93	DATE OPENED 06/10/93	DATE CODE RR 11-68	SERIAL NUMBER 379389	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN	BDL	
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS			
FROM: <i>Setup full</i> BRAUN, FRED SPORTING GOODS 405 OVERLAND STREET KENAI AK 99611				SHIP TO: BRAUN, FRED SPORTING GOODS 405 OVERLAND STREET KENAI AK 99611			
CUST NO: 079973 C.Q.D							
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	FROM DATE	ESTIMATED	VIA UPS		
GUN CONDITION			REPAIR CHARGE <i>2500</i>				
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			EXCISE TAX INSURANCE UPS PARCEL POST TOTAL				
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	N	B1					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD				D3	E5	F5	
METAL			C2				
MAIN FAULT <i>Left only 1968 upon receipt rifle does not cock, firing pin follows down. Examination revealed that the trigger adjustment and stop screw have been altered without history. Also found trigger pin rusty.</i>							
PARTS				COMMENTS <i>Replace trigger assembly completely and clean action at 1/2 normal adjustment cost at discretion of your mfr. Go ahead</i>			
REPAIRMAN <i>BFA</i>				PROOF	CLEAN	TEST	TARGET
GALLERY TESTER				DATE	DATE	DATE	DATE