(P E & C)

(R & D) Substitute Materials


A. Urethanes

B. Plastics

C. Others

Finishing techniques - to be required with any or all of above.

A. Masking natural appearance - Uvion
B. Subduing natural grain
C. Accentuating natural grain
D. Selective densification



1